

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: CB 6539C

at Workshop m/s V-TR

of 1, Susan Lee ST #06-45/05

Insured: YP 9525M CTI

Policy No. DMCVSNW00092442200

Claims No. SNM22D209246/C02/TANKL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.

①	
N/S	O/S

Bal. or Market Value: 56k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: CB 6539C Yr Regn: 2010 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MINI-VAN

Make: MERCEDES BENZ S15 CD14235 c.c 2148

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 648954 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: web90665725315062

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NR / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 23/12/22 D.O.I. 27/12/22

Survey held at V-TR

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis/frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 56K

30/12/22 ESTIMATE RANGE OF REPAIR (no. of days - (6K-7K) / 7 days

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

1) _____
Date/Time, File Return to?

2) 30/12/22-typist

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Transportation: _____

S + RS _____ \$

Photos _____

Others _____

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC
Owner ID: 915G

Vehicle No: CB6539C
Vehicle to be Exported: No
Intended Deregistration Date: 28 Dec 2022
Vehicle Make: MERCEDES BENZ
Vehicle Model: 515CDI/4325
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 64698651600768
Chassis No.: WDB90665725315062
Maximum Power Output: -
Open Market Value: \$79,847.00
Original Registration Date: 23 Jul 2010
First Registration Date: 23 Jul 2010
Transfer Count: 1
Actual ARF Paid: \$3,993.00

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

COE Rebate Amount: \$0.00
Total Rebate Amount: \$0.00

The information contained herein is correct as at 28 Dec 2022

OK