

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL		Ref:	CS/AGI22012860/Rvy3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE		Date:	08/03/2023	
				Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJZ 4507Z	Veh. Inspected		GBF 9990C	
	Policy No.	P10519175R02	Coverage (\$)		0.00	
	Claim No.	C10019113 /CD	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		27/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE 5 DR M	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTFHT02P500200934	Colour		GREY	
	Odometer	170518 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	01/12/2022	Inspection Date)	28/12/2022	
	Survey held at	vey held at 160 SIN MING DRIVE #05-21 SIN MING AUTOCITY				
	Repairer	EM-1 AUTO PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: