

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4801m
 MAKE 25.10.2019
 MODEL IONIQ G3

20.10.2022

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40 <i>de</i>
1	REAR BUMPER CENTRE MOULDING			\$451.25 <i>de</i>
1	REAR BUMPER REINFORCEMENT			\$394.80 <i>cur</i>
2	REAR BUMPER STAY LH/RH		\$138.10	\$276.20 <i>CHX</i>
10	REAR BUMPER CLIPS		\$2.20	\$22.00 <i>all</i>
1	REAR BUMPER LOWER CENTRE MOULDING			\$155.00 <i>xm</i>
1	REAR BUMPER UNDER CENTRE COVER			\$225.00 <i>xm</i>
1	REAR BUMPER SIDE UNDER COVER LH			\$108.00 <i>h</i>
1	BOOTLID H EMBLEM			\$38.00 <i>de</i>
1	BOOTLID EMBLEM IONID			\$31.80 <i>de</i>
1	BOOTLID EMBLEM HYBRID			\$24.30 <i>de</i>
1	REAR BUMPER TOW COVER			\$98.80 <i>all</i>
1	REAR BUMPER REFLECTOR LH			\$41.45 <i>set</i>
1	REAR BUMPER FOG LAMP			\$201.50 <i>xm</i>
2	REAR NUMBER PLATE LAMP		\$42.65	\$85.30 <i>xm</i>
2	REAR BUMPER BRACKET LH/RH		\$55.80	\$111.60 <i>de</i>
			1725.60	\$2,724.40
			1380.48	\$544.88
	DISCOUNTED TOTAL			\$2,179.52
1	BOOTLID COMFORT APP STICKER			\$40.00 <i>de</i>
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00 <i>de</i>
1	BOOTLID ADVERTISEMENT			\$100.00 <i>de</i>
1	REAR FENDER ADVERTISEMENT		\$100.00	\$200.00 <i>de</i>
1	REAR BUMPER MAT			\$50.00 <i>de</i>
1	REAR NUMBER PLATE W/HOLDER			\$55.00 <i>xm</i>
1	REAR REVERSE SENSOR			\$180.00 <i>nm</i>
				\$651.50
	Labour Charge			
	Panel Beating			\$1,050.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Check wiring and lighting			\$60.00 <i>xm</i>
	Tuff Kote			\$90.00 <i>xm</i>
	Remove/Refix reverse sensor			\$60.00 <i>30</i>
			1055	\$1,860.00
	TOTAL LABOUR			
	ESTIMATE TOTAL		3037.48	\$4,691.02
			1150	
			2450	
			3 days #	

LKK Auto Consultants
 I hereby notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Tanfer 979 95449
 info 20/10/14 30 pm
 us rising after repair
 tanfer@lkkcamb.com
 2-3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.