

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

DATE 20.10.2022

VEHICLE NO SHA4758X

MAKE 30.12.2016

MODEL PRIUS G4

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			<del>PX</del> \$499.90
1	FRTBUMPER CENTRE GRILLE			<del>u1</del> x \$318.80
1	FRT RAD GRILLE			<del>u1</del> x \$88.00
1	FRT BUMPER TOW COVER			<del>u1</del> x \$28.38
1	FRT GRILLE EMBLEM			<del>u1</del> \$43.80
1	FRT NO PLATE EXT GARNISH			<del>de</del> \$99.00
1	FRT BUMPER SIDE RETAINER RH /LH		\$77.00	<del>u1</del> x \$154.00
	<b>SUB TOTAL</b>		142.80	<b>\$1,231.88</b>
	<b>LESS 25%</b>		107.10	<b>\$307.97</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$923.91</b>
1	FRONT NUMBER PLATE&W/HOLDER		55	<del>ht</del> \$55.00
				<b>\$45.00</b>
	<b>Labour Charge</b>			350 \$550.00
	Panel Beating			250 \$500.00
	Spray Painting Charge			<del>u1</del> \$60.00
	Check Wiring		600	<del>u1</del> \$60.00
	tuff coat			<b>\$1,170.00</b>
	<b>TOTAL LABOUR</b>		762.60	
	<b>ESTIMATE TOTAL</b>		1134.60	<b>\$1,238.91</b>
			. 2 days	
			<del>*</del>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanglin 47495747  
 'up' 20/10/22 05pm  
 02 days  
 1/2 way after repair  
 fup @ 01/11/22