

ASS. REC BY: T. G. J. M.

REF:

INC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SHA 4758X Yr Regn: 2016 REC.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Prius C.D. 1798
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 507199 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STDURB3FY 503536813
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: M/L / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 195/65R15
R: 195/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westerlake
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 20/04/22
Survey held at Conquest Agency
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report

Date/Time, File Return to?
2) _____

Report Format : _____
Lump Sum / L.B.K. / _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS. SI.	
Photos	
Others	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4758X

DATE 20.10.2022

MAKE 30.12.2016

MODEL PRIUS G4

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			PK \$499.90
1	FRTBUMPER CENTRE GRILLE			u1x \$318.80
1	FRT RAD GRILLE			u4x \$88.00
1	FRT BUMPER TOW COVER			u1x \$28.38
1	FRT GRILLE EMBLEM			u1x \$43.80
1	FRT NO PLATE EXT GARNISH			de- \$99.00
1	FRT BUMPER SIDE RETAINER RH /LH		\$77.00	u1x \$154.00
	SUB TOTAL		142.80	\$1,231.88
	LESS 25%		107.10	\$307.97
	DISCOUNTED TOTAL			\$923.91
1	FRONT NUMBER PLATE&W/HOLDER		55	ht- \$55.00
				\$45.00
	Labour Charge			
	Panel Beating		350	\$550.00
	Spray Painting Charge		250	\$500.00
	Check Wiring		u1x	\$60.00
	tuff coat		600	u1x \$60.00
	TOTAL LABOUR		762.60	\$1,170.00
	ESTIMATE TOTAL		1184600	\$1,238.91
			.2 days	
			*	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanglin 47495747
 'up' 20/10/22 05pm
 02 days
 1/10 busy after inspect
 further @ Chhachhachh

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road Singapore 708649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768731

Date/Time: 20.10.2022 16:14

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5069099

JC NO: 305533787

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

.. (R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO:

SHA4758X

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)20.10.2022 15:00

DATE/TIME IN

YR OF MANU.

30.12.2016

TARGET DATE

CHASSIS CODE

JTDKB3FU503536813

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.10.2022


NATURE: 3P 20.10.2022

S/NO

LABOR CODE

DESCRIPTION

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHA4758X

CHIANG

Vehicle No.:

SHA4758X

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard