

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22012904/Twy3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date: Code:	03-01-2023 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMH 686A	Veh. Ir	spected	SHA 8484J	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1191456-003	Exces	,	0.00	
	Assign From		Assign	n Date	04/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	C.C		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU103562888	Colou	•	YELLOW	
	Odometer	707145	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	ccident Date 03/10/2022 Inspection Date 04/10/2022				
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					