

ASS. REC BY: T. J. M.

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Mr. Lowe Vehicle: IN / OUT

Veh No:

SHVA 84843

Yr Regn:

2017 Sep

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Royal Enfield

C.C.

1748

Colour

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

707145

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STDK13F4103562888

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

4/10/22

Survey held at

Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: _____

Lump Sum / L.B. / %

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA8484J

Make : Toyota

Model : Prius

Date: 04/10/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$ 503.04
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER REINFORCEMENT			\$ 378.32
1	REAR BUMPER LOWER COVER			\$ 654.96
			676.96	
			507.72	
	SUB TOTAL			\$ 1,558.32
	LESS 25%			\$ 389.58
	DISCOUNTED TOTAL			\$ 1,168.74
	RENEW ADVERTISEMENT STICKER		250	\$ 250.00
				\$ 250.00
	Labour Charge			
	PANEL BEATING		630	\$ 400.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR		1387.72	\$ 760.00
	ESTIMATE TOTAL		4581.100	\$ 2,178.74
			2 days	

Rv
net
Xun
cutnet
Nett350
250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphu 97495749
w/ 4/10/2022 230pm
L/S Rung after repair
2 days
Tanphu Lohando. w

- K Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 04.10.2022 12:38

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4944813

JC NO 05532125

STOMER

/MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (R) (O)
(P)

COUNT CARD NO.

REGN NO.:

SHA8484J

MILEAGE

MAKE:

TOYOTA

FUEL

E..... 1/2..... F

MODEL

PRIUS HYBRID(G4)04.10.2022 08:20

DATE/TIME IN

YR OF MANU.

13.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU103562888


COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 03.10.2022
NATURE: 3P 03.10.2022

'NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA8484J

YY

Vehicle No.:

SHA8484J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard