

Our Job Ref No :			305540936					
Date		30.12.22					elGro Engineering Pte Ltd g Drive Singapore 508969 § 8156	
FINALIZATION FORM								
То	:	LKK Fax:						
Attn	Attn : MrRASUL				_			
Vehicle Reg No. SH67			55Z		Dat	e of Accide	ent :	27.12.22
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-								
1.	1. The repair job shall bill 703			ток	0	(442		SMY1601Z
2.	The fi	nalized amount s	shall be:					
	(a) Spare Parts after List discount							
	(b)	Labour Charges	3					
		Total for Part-E	By-Part Repair C	ost) -
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost							\$900.00
 Estimated normal period for repairs: 2 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days Thank you for your assistance. We confirm the estimates and 								
	Signature :				Signature: RASUL			
								J1/23
	Fax	: 65468156	6					
For Official Use Only								
	Item		Amou	nt /	ocument Attached es or No	Confirm By (Signature)		Remarks
Rental Rate P/Day					YES			
2. Loss of Income Paid			J 		NO			
3. Survey Fees			3222		3224			
LTA Search Fee 5. Medical Fees (on behalf of driver, if applicable) 6 Overrun			\$7.49 / \$	2.00	YES			
Remarks:								
	:							