

Our Job Ref No : 305540937
Date : 06.01.2023

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RASUL

Vehicle Reg No. : SHA4519U

Date of Accident : 24.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ INS --- SFL6236M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$4,750.00

Final Lumpsum Repair cost \$4,750.00

3. Estimated normal period for repairs: 8 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Signature : _____

Name : LIM T S

Name : RASUL

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

