



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012910/Uny3q2	
			Date: 11/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 3735H	Veh. Inspected	PD 572E	
Policy No.	D22MTPCVE001237	Coverage (\$)	0.00	
Claim No.	CMTD2204721/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	27/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ VIANO (A)	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDF63981523676821	Colour	BLACK	
Odometer	155223 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	HABILEAD	7 mm	
L/H Front Tyre	215/65 R16	HABILEAD	7 mm	
R/H Rear Tyre	215/65 R16	HABILEAD	7 mm	
L/H Rear Tyre	215/65 R16	HABILEAD	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2022	Inspection Date	03/01/2023	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	