



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22012918/Awy3e2 Date: 31/03/2023  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMF 5928E	Veh. Inspected	SJW 8864G	
Policy No.	P10473999R02	Coverage (\$)	0.00	
Claim No.	C10019421 /KY	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	28/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA1V720X0V724791	Colour	BLUE	
Odometer	97225 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/12/2022	Inspection Date	28/12/2022	
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	