

(08/11/13) wef

ASS. REC. BY: PM

REF:

CS/MSG 22012922 Rvy3

8713

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFS 7739Kat Workshop m/s AUTOSPRINT P/Lof 24, LENH KEE RD #07-01/02Insured: MSG

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

95K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LM17-63K

Veh No:

SFS 7739K

Yr Regn:

2019 / NOVType: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA SIENNA 1.5G CVT c.c. 1496

Colour:

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

36759

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

N5P 170 7209 605Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FRANK

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/12/22

D.O.I.

29/12/22

Survey held at

AUTOSPRINTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS _ \$

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

)

QUOTATION

To: **CANDY**
SFS7739K, TOYOTA, SIENTA 1.5G CVT

Our Ref : Q221209
Date : 23 Dec 2022

Attn : **CANDY (81981677)**

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party claims SFS7739K against GBL2253L

No.	Description	Qty	UOM	U/P (\$)	Amt (\$)
Ad hoc					
1	Rear Tail Gate <i>st/</i>	1.00		700.00	700.00
2	Rear Tail Gate Inner Lock <i>?</i>	1.00		262.50	262.50
3	Rear Tail Gate Outer Handle <i>?</i>	1.00		167.00	167.00
4	Rear Windscreen Glass <i>no photo</i>	1.00		735.00	735.00
5	Rear Windscreen Moulding <i>no</i>	2.00		35.00	70.00
6	Rear Windscreen Sealant <i>no</i>	1.00		60.00	60.00
7	Rear Bumper <i>dam repair</i>	1.00		280.00	280.00
8	Rear Bumper Retaining Screw <i>no</i>	4.00		17.50	70.00
9	Rear Bumper Clips <i>no</i>	1.00		26.00	26.00
10	Rear Bumper Top <i>de</i>	1.00		131.25	131.25
11	R/H Rear Reverse Lamp <i>crn</i>	1.00		245.00	245.00
12	Labour Charge to straighten rear lower inner panel, replace the above listed damaged parts <i>250 @ 320 X 2</i>	1.00		800.00	800.00
13	Labour Charge to replace rear windscreen glass	1.00		120 140	140.00
14	Labour Charge to reconnect rear lamp wire harness, reinstall third brake lamp & check for proper function	1.00		30 60	60.00
15	Labour Charge to spray painting on the affected parts & areas.	1.00		500 600	600.00
16	Rear Wiper Motor <i>X</i>	1.00		507.00	507.00
17	Rear Bumper Sensors <i>? s/n</i>	1.00		200 280	280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Rasul
Hp 90010068
4 days
P/P
29/12/22 P of 30
Reg 64 pint

Subtotal: 5,133.75
GST 7.0% : 359.37
Total Amount: 5,493.12

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	871J
Vehicle Details	
Vehicle No.:	SF57739K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2NR1144007
Chassis No.:	NSP1707209605
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$23,062.00
Original Registration Date:	18 Nov 2019
First Registration Date:	18 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$14,287.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2029
PARF Rebate Amount:	\$10,715.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,000.00
COE Rebate Amount:	\$20,625.00
Total Rebate Amount:	\$31,340.00

Toyota Sienta 1.5A G

Overview

Financial

Accessories

Similar

Research

Photos

Map

AN AWARD-WINNING PREMIER AUTOMOTIVE HOUSE



Price

\$97,800

Depreciation ⓘ

\$13,060 /yr

[View models with similar depre](#)

Reg Date

30-Dec-2019

(6yrs 11mths 27days COE left)

Mileage

26,000 km (8.6k /yr)

Manufactured ⓘ

2019

Road Tax ⓘ

\$682 /yr

Transmission

Auto

Dereg Value ⓘ

\$32,247 as of today ([change](#))

OMV ⓘ

\$22,046

COE ⓘ

\$32,309

ARF ⓘ

\$12,865

Engine Cap

1,496 cc

Power

80.0 kW (107 bhp)

Curb Weight ⓘ

1,320 kg

No. of Owners ⓘ

1