

(08/11/13) wef

ASS. REC. BY:

REF:

CS3/AIS22012926/GVY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 389G

at Workshop m/s Hong Motor

of _____

Insured: YN 2488T

Policy No. _____

Claims No. 2022 22009140


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh. had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 389G Yr Regn: 2 / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey 24c.c 2356

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC 1890GC * 201770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/10/22 D.O.I. 28/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair range 5k to 6k. with 5 day..

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	078G
Vehicle Details	
Vehicle No.:	SLA389G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2023
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	K24W72010780
Chassis No.:	JHMRC1890GC201770
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,389.00
Original Registration Date:	19 Feb 2016
First Registration Date:	19 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$31,745.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2026
PARF Rebate Amount:	\$20,634.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,920.00
COE Rebate Amount:	\$17,064.00
Total Rebate Amount:	\$37,698.00

The information contained herein is correct as at 10 Jan 2023

OK