



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                  |                 |                                                           |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|-----------------|-----------------------------------------------------------|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705                                              |                                                  |                 | Ref: CS/SMR22012927/Gvy3<br>Date: 28/12/2022<br>Code: SMR |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                  |                 |                                                           |  |
| Insured Veh.                                                                                                                           | SMB 1464Z                                        | Veh. Inspected  | PC 2449X                                                  |  |
| Policy No.                                                                                                                             |                                                  | Coverage (\$)   | 0.00                                                      |  |
| Claim No.                                                                                                                              | BUS/12/22/5033                                   | Excess (\$)     | 0.00                                                      |  |
| Assign From                                                                                                                            | HUA YEN                                          | Assign Date     | 28/12/2022                                                |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                  |                 |                                                           |  |
| Make & Model                                                                                                                           |                                                  | c.c             | 0                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                           | Year of Reg.    |                                                           |  |
| Chassis No.                                                                                                                            |                                                  | Colour          |                                                           |  |
| Odometer                                                                                                                               | -                                                | Steering        |                                                           |  |
| Brakes                                                                                                                                 |                                                  | Modification    |                                                           |  |
| General                                                                                                                                |                                                  |                 |                                                           |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                  |                 |                                                           |  |
|                                                                                                                                        | Size                                             | Make            | Balance                                                   |  |
| R/H Front Tyre                                                                                                                         |                                                  |                 | mm                                                        |  |
| L/H Front Tyre                                                                                                                         |                                                  |                 | mm                                                        |  |
| R/H Rear Tyre                                                                                                                          |                                                  |                 | mm                                                        |  |
| L/H Rear Tyre                                                                                                                          |                                                  |                 | mm                                                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                  |                 |                                                           |  |
|                                                                                                                                        |                                                  |                 |                                                           |  |
| <b>5. General Information</b>                                                                                                          |                                                  |                 |                                                           |  |
| Accident Date                                                                                                                          | 21/12/2022                                       | Inspection Date | 28/12/2022                                                |  |
| Survey held at                                                                                                                         | 3 Temasek Boulevard #01-330 Suntec Shopping Mall |                 |                                                           |  |
| Repairer                                                                                                                               | BOXFRESH PTE LTD                                 |                 |                                                           |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                  |                 |                                                           |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                  |                 |                                                           |  |