

(08/11/13) wef
ASS. REC. BY: *jsm*

REF: *CS/CTI 22012932/RVP3*

847F

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKX 7489X*
at Workshop m/s *Volkswagen*
of *247, MCGOWAN RD*
Insured: *CTI*

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *142K*

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKX 7489X* Yr Regn: *2019 / M44*
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: *Volkswagen GTI Golf 2.0 5R C.C. 1984*

Colour: *WHITE* A/C: Insured / Std / NI / NA

Sp. Reading: *48608* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WVWZ22AUZKW111756*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *225/40R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *23/12/22* D.O.I. *30/12/22*

Survey held at *VOLKSWAGEN*

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR U/C - 80K

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



30/12/2022

Survey @ 9-30am

Quotation

Non binding - Preview

Page

1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
REENA
D/O KUNJI RAMAN
MRS.REENA SURESH
27 CASUARINA WALK
Singapore 574085

Document no.
Document date 27-12-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022037699/ 1
Job order date 27-12-2022
Service Advisor Hui Wen Oh

License plate	Model code	First registration	VIN	Model	Mileage
SKX7489X	BQ19UYG0	31-05-2019	WVWZZZAUZKW111756	Golf 2.0 GTI 169TSI D6F	43,547

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5G0853675Q 2ZZ	Inscription Bright Chrome	1	pcs.	97.17	#1	97.17	103.97
	REAR BOOT LID NAME PLATE - GTI	1	pcs.	1,190.76	#1	1,190.76	1,274.11
5G6807417BQGRU	Cover For Bumper Primed REAR BUMPER	1	pcs.	34.83	#1	34.83	37.27
5G6807441A GRU	Cover For Towing Eye Prim	1	pcs.	750.84	#1	750.84	803.40
5G0807305D	Bumper REINFORCEMENT	1	pcs.	73.18	#1	73.18	78.30
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	43.33	#1	43.33	46.36
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	#1	43.33	46.36
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	#1	43.33	46.36
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	#1	43.33	46.36
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	14.79	#1	14.79	15.83
5G0919397B	Sensor Bracket	1	pcs.	14.79	#1	14.79	15.83
5G0919398B	Sensor Bracket	2	pcs.	14.29	#1	28.58	30.58
5G0919491D	Sensor Bracket	1	pcs.	14.29	#1	14.29	15.29
5G0919491E	Sensor Bracket	1	pcs.	14.93	#1	14.93	15.98
5G0919492D	Sensor Bracket	2	pcs.	190.18	#1	380.36	406.99
5Q0919275B GRU	Sensor Primed	2	pcs.	1.46	#1	2.92	3.12
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	85.94	#1	85.94	91.96
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	68.85	#1	68.85	73.67
D 822150A1	Bonding Agent For Plastic	2	pcs.	64.07	#1	128.14	137.11
3G5943021	Led Licence Place Light	1	pcs.	81.02	#1	81.02	86.69
5G0945106C	Reflector RH	1	pcs.	1,340.79	#1	1,340.79	1,434.65
5G0071610D GRU	Rear Apron Attachment Wit BUMPER LOWER BODY KIT	1	pcs.	63.31	#1	63.31	67.74
000071785D	Adhesive Kit For Aerodyna LABOUR	1	pcs.	840.00	#1	840.00	2,696.40
	SPRAY PAINT	1	pcs.	800.00	#1	800.00	3,424.00
	DESCRIPTION: DIRECT ASIA VS CHINA TAIPING						
	DOA: 23/12/2022						
	TP VEH NO: SNG9792K						
	SURVEY BY:						

Quotation valid till 03-01-2023

* If spray then need add on spray paint Labour!

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
REENA
D/O KUNJI RAMAN
MRS.REENA SURESH
27 CASUARINA WALK
Singapore 574085

Document no.
Document date 27-12-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022037699/ 1
Job order date 27-12-2022
Service Advisor Hui Wen Oh

License plate	Model code	First registration	VIN	Model	Mileage
SKX7489X	BQ19UYG0	31-05-2019	WWWZZZAUZKW111756	Golf 2.0 GTIBM 169TSI D6F	43,547

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	10,278.81	7%	772.72	11,038.81	11,811.53
Total	760.00	10,278.81		772.72	11,038.81	11,811.53

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
3 days
30/12/22 0950
Res before put

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 847F

Vehicle Details

Vehicle No.: SKX7489X
Vehicle to be Exported: No
Intended Deregistration Date: 02 Jan 2023
Vehicle Make: VOLKSWAGEN
Vehicle Model: GOLF GTI 2.0 DSG
Primary Colour: White
Manufacturing Year: 2019
Engine No.: CHH304767
Chassis No.: VWWZZZAUZKW111756
Maximum Power Output: 169.0 kW (226 bhp)
Open Market Value: \$35,044.00
Original Registration Date: 31 May 2019
First Registration Date: 31 May 2019
Transfer Count: 0
Actual ARF Paid: \$41,062.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 May 2029
PARF Rebate Amount: \$30,796.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2029
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$52,502.00
COE Rebate Amount: \$30,767.00
Total Rebate Amount: \$61,563.00

Volkswagen Golf GTI 5DR Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



AUTOPRESTIGE GALLERY

YOUR LUXURY AUTOMOBILE GALLERY

Price **\$141,000**

Depreciation  \$19,150 /yr
[View models with similar depre](#)

Reg Date 24-Apr-2019
(6yrs 3mths 21days COE left)

Mileage 31,678 km (8.6k /yr)

Manufactured  2018

Road Tax  \$1,194 /yr

Transmission Auto

Dereg Value  \$60,539 as of today ([change](#))

OMV  \$34,526

COE  \$48,000

ARF  \$40,337

Engine Cap 1,984 cc

Power 169.0 kW (226 bhp)

Curb Weight  1,408 kg

No. of Owners  1