

Your Ref: 18/19/19/VP02/282155

Date: 23rd February 2023

Our Ref: CS1/LPM22012946/Dqy3m4

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMK 1255M
INSURED VEHICLE: WB 8918Q
ACCIDENT DATE: 13/04/2019**

We thank you for your instruction on 23/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMK 1255M from M/s T & C Automobile Assessors.
- b) Police Report of Vehicles SMK 1255M and WB 8918Q.
- c) Colour damaged vehicle photographs of SMK 1255M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMK 1255M
Make & Model	: Honda Shuttle Hybrid 1.5 Auto
Chassis Number	: GP72002518
Year of Registration	: 2019
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.