

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C7/2201294914

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 8082B

at Workshop m/s Sanyu

of \_\_\_\_\_

Insured: SMT2642A

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 174822081

Veh No: SLB 8082B Yr Regn: 28/04/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mude vazel c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 90308 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU1111 0070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 7AUKY

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 23/1/22 D.O.I. 3/1/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 12h.
	No Estimate PPS
	Summary on 3-1-23 @ 10.45am
	Disa the on 3-1-23 @ 2.35pm

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	261H
Vehicle Details	
Vehicle No.:	SLB8682B
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2023
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B4030075
Chassis No.:	RU11110070
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,852.00
Original Registration Date:	25 Apr 2016
First Registration Date:	25 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,852.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2026
PARF Rebate Amount:	\$6,403.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$15,648.00
Total Rebate Amount:	\$22,051.00

The information contained herein is correct as at 03 Jan 2023

OK





From now till 8 Feb  
Stand a chance to win a  
**\$250 Shell Fuel Voucher every week!**

[Join Now!](#)

Proudly supported by

**Post an Advertisement**

Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**BMW 5 Series 528i.**

Very Low Mileage. Excellent  
Condition. Kept  
Indoors/covered.  
Direct Owner StarAd



**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997**[View our cars](#)[Back \( 1 2 3 4 5 \) Next »](#)Sort by [Date Posted](#) [20](#) results/page

97 vehicles



Honda Vezel

Any Category

Advanced Search



Search

</