

REF: CS3/CTI22007592/Tnp3-1

Special Instruction:

L/SUM: 32,400 / REPAIR: 14 WORKING DAYS

Third Parties:

Claimant:

Surveyor: RELIANCE APPRAISAL

Workshop:CHIP SOON AUTO SUPPLY CO

ASSIGNMENT (Office)

From (Person): CECILIA LEE of CTI Date/Time: _____

Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLZ 8701D Insured: GBK 9969P

at Workshop m/s CHIP SOON AUTO SUPPLY CO.

of BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 08/08/2022

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 18/01/23 Confirmed with _____ Final Fig _____, ____ days (Red S ____/____%; Original! ____ days)

Date/Time: 18/01/23 Submit Final Fig 24400, 14 days (Red \$ 8000 / 25 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____