

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/01/2021 10:08 (SGT)
Date of Accident 21/01/2021 11:00 (SGT)
Exact Location of Accident 1 Selarang Ring Rd, Singapore 507087
Additional Location Information SELARANG CAMP GUARDROOM.
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH6663G

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner MCS LOGISTICS (S) PTE LTD
Company Reg No 1XXXXX210D
Email Address christina@mcslogs.com
Mobile Phone No (Phone) +65-94878823
Alternative Phone No +65-94878823

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv200
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company NTUC
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5118610884
Cover Note Number -

DRIVER

Name of Driver TAY WAN TIONG
NRIC No SXXXX528H
Date Of Birth 15/05/1953
Occupation Indoor

Date Of Driving Pass	01/08/1974
Driving experience	46 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97429489
Alt. Phone Number	-
Email Address	christina@mcslogs.com
Address	BLK 175 YUNG KUANG ROAD #19-37
Address complement	-
Postcode	613175
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

TRAFFIC LIGHT TURNS GREEN, I PROCEED TO ENTER THE CAMP WHEN SUDDENLY THE UNDERGROUND BARRIER RAISES UP AND HIT ONTO MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Traffic light was green, I passed the car when
suddenly the red light came on and the car
stopped.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

N. Hay

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

IMAGES





















ADDENDUM FORM

**GENERAL
INSURANCE
ASSOCIATION**

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Matheson Quay #18-01 Singapore 050181
Tel: (65) 6324 0350 Fax: (65) 6324 0019
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S66SSD0206 / GST Reg. No: M450001771

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: SS1Y211M0004 Vehicle Registration No: GBM 6634
Name (as shown in NRIC): THY HAN TIONG NRIC/FIN/Passport No: 801265081
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: RT 1-15 YUNKEE KURNER RD #119-27 Singapore (60000)
Contact (Tel): _____ Mobile No: 9747 7189
Email Address: christina@mcsl.org.com
Date of Accident: 21/01/2021 Time of Accident: 11:00
Place of Accident: SELARANGI CAMP BUNKER ROOM
Insurance Company: HIUL

(B) ADDITIONAL INFORMATION / AMENDMENTS:


I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

CHANGE TO THIRD PARTY CLAIM.

Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name
NRIC/FIN No
Date



THE SCHEDULE

Commercial Vehicle Insurance Policy

This Policy (Policy) and the terms and conditions of the Singapore Motor Vehicle Insurance Corporation Limited (SICOM) and you (the insured) are incorporated into this Schedule to this Policy.

The statements, information and details stated previously by you at the time of proposal (proposal) and the details of this accident (accident) will be used to determine the insurance settlement in the event of a claim occurring during the term of this policy. The terms of this Schedule and any further (period for which we may accept a renewal premium) the proceeds of this insurance is subject to:

1. any endorsement specified as operative in the schedule;
2. the Conditions and Exclusions to Insurers of this Policy; and
3. the payment of the premium specified in the schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.
SICOM No. M00372806G.

Policy Number	4118970444
Insured/Insureds	MUNDO (S) TRADING PTE LTD 1 KARI BURR ROAD 404-06 LUNGS WAREHOUSE COMPLEX SINGAPORE 417675
Period of Insurance	27 Aug 2020 to 26 Aug 2021
Sum Insured	Market Value of Insured Vehicle at time of loss
Premium (inclusive GST)	S\$1,420.73
Interest Insured	
Cover Type	Comprehensive
Make/Model	NISSAN/NAV200
Capacity	0.80 tons
Registration Number	GBH6664G
Chassis Number	NSKRYBA12070170224
Excess (Section 1)	S\$500
Excess (Section 2)	N/A
Windscreen Excess	S\$100
Hire Purchase Company	DBS BANK LTD
Number of Seater	2
Registration Date	27 Aug 2018
Insured with CEI	Yes
VED Entitlement	15%

Memo A : N/A

Endorsement Operative : N/A

Agency: M&M Insurance Agency (00003571869)
Date of Issue: 12 Aug 2020 11:10 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and fairly, all the facts you know or ought to know. Otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors

Chief Executive



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C




Proforma Invoice

MCS Logistics (S) Pte Ltd
No.1 Kaki Bukit Road 2
#04-06 Eunos Warehouse Complex
Singapore 417835
Tel: 6846-4262
Fax: 6745-5065
Attn: Accounts Department (Mr Yong)

No. : PI.21/000011
Date : 18/06/2021
Ref. : 31742-GBH6663G-210301
Staff : Jaclyn Lai
Terms : 30 Days
Job : 31742-GBH6663G210301

GBH6663G - NISSAN NV200

SNo	Description	Quantity	Unit Price	Amount
1.	<p>Veh. Owner Name : MCS Logistics (S) Pte Ltd Make & Model : NISSAN NV200 1.5 MT Chassis No. : VSKYBAM20Z0170224 Engine No. : K9KE628D608258 LTA Reg. Date : 27.08.2018</p> <p>Date Of Accident : 21.01.2021</p> <p>Claim Type : Third Party Claim Our Ref : asm/AC21019/JL</p> <p>Being Lump-Sum Charges for Accident Repair & To Replace All Necessary Items.</p>	1	5,850.00	5,850.00
Sum of Singapore Dollars Six Thousand Two Hundred Fifty Nine And Cents Fifty Only			Amt S\$ 7% GST Total S\$	5,850.00 409.50 6,259.50


Authorised Signature



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO.
MCS LOGISTICS (S) PTE LTD C/O ASM AUTOMOTIVE SERVICES PTE LTD NO 13 PIONEER SECTOR 1 SINGAPORE 628424

DATE	INVOICE NO.
8/3/2021	A 42752

DESCRIPTION	VHA NO.	DUE DATE	VEH NO.
	A 42752	8/3/2021	GBG 2809 K
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 01 MARCH 2021 TO 04 MARCH 2021 YOUR REF: GBH 6663 G	3	120.00	360.00
Account Name: BKW RENT A CAR PTE LTD Account No: 118-312-9991 Bank: UNITED OVERSEAS BANK LTD (UOB) Branch: UOB Shaw Centre Branch Bank Address: 1 Scotts Road #03-04 Shaw Centre Singapore 228208 Bank Code: 7375 Branch Code: 018 Swift Code: UOVBSGSG All cheques must be made payable to BKW RENT A CAR PTE LTD. *Please indicate the invoice number and vehicle number in the reference.	Subtotal	\$360.00	
	GST @ 7%	\$25.20	
	TOTAL	\$385.20	



bizSAFE



PRIORITY SERVICES (SG) PTE LTD

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

Messrs. MCS Logistics (S) Pte Ltd
1 Kaki Bukit Road 2
#04-06 Eunus Warehouse Complex
Singapore 417835

Bill No : DN/00018/21

Date : 20/4/2021

Dr.

To

Survey Fee (S\$) : 746.00
Photographs (S\$) :
Transport (S\$) :
Resurvey (S\$) :
Miscellaneous (S\$) :

Services rendered including photographs and transport charges

(S\$) : 746.00

Our Reference : IN-0003/04/21
Insured :
Date Of Accident : 21/01/2021
Policy / Cert. No. :
Your Claim No : Third Party Claim
Vehicle : Nissan NV200 (M) - GBH 6663 G

Dollars : Seven Hundred Forty Six ONLY

For PRIORITY SERVICES (SG) PTE LTD

E & O.E.



PRIORITY SERVICES (SG) PTE LTD

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

Vehicle Inspection Report

Report No. IN-0003/04/21	Date of Report	: 20/04/2021
To : MCS Logistics (S) Pte Ltd	Date of Request	: 01/03/2021
1 Kaki Bukit Road 2	Report requested by	: MCS Logistics (S) Pte Ltd
#04-06 Eunus Warehouse Complex	Date of Inspection	: 01/03/2021
Singapore 417835	Date of Accident	: 21/01/2021
Policy No :	Sum Insured	-
Claim No : Third Party Claim	Excess (S\$)	: N/A
	Insured Vehicle	

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: GBH 6663 G	Odometer Reading	: 94185 km
Make / Model	: Nissan NV200 (M)	Radio / CD	: Yes
Year	: 2018	Air-conditioner	: Yes
Colour	: Met. Grey	Wing Mirror	: Yes
Engine Capacity	: 1461 cc	View Cam	: Yes
Engine No	: -	Seat Belts	: Yes
Chassis / Frame No	: VSKYBAM20Z0170224	Accessories	: -
Carrying Capacity	: 3100 kg		

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Grenlander	Make	: Grenlander
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Grenlander	Make	: Grenlander
Spare	:	Road Wheels Type	: Standard

(The above represents the approximate remaining life of tyre treads)

Tools	: Intact	Spare tyre	: Intact
-------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (static tests only)

General bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.



PRIORITY SERVICES (SG) PTE LTD

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

ASSESSMENT

		Repairer's Estimate (S\$)	Our Recommendation (S\$)
Spare Parts	:	11,370.20	5,552.80
Labour Charges	:	2,530.00	1,460.00
Paint Work	:	350.00	300.00
Towing Charges	:	0.00	0.00
Others	:		
Totals	:	14,250.20	7,312.80

Reduction (S\$) : 8,400.20

Recommended Reserve (S\$) : 5,850.00 (Lump Sum)

Estimated Normal Period of Repairs : 5 working days

CONTRIBUTIONS BY INSURED

Excess (S\$) : N/A

Others :

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. ASM Automotive Services Pte Ltd, No. 13 Pioneer Sector 1, Singapore 628424
Follow-up inspection has been conducted.

Point of Impact

At the front portion.

Damages

The front bumper, front bumper reinforcement, front bumper sponge, intercooler, radiator grille lower garnish, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$7,312.80

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$5,850.00

Pre-accident market value : About \$59,000.00

COE rebate from LTA : \$22,571.00 (COE expiry on 26-08-2028)

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES (SG) PTE LTD



LAWRENCE NG, MSAAA
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : GBH 6663 G Nissan NV200 (M)
Workshop : ASM Automotive Services Pte Ltd

IN-0003/04/21

Description	Condition	Repairer's Estimate (S\$)	Dist %	Our Recommendation (S\$)	Dist %
To Supply :					
1pc. radiator grille	refit	460.00	10	0.00	10
1pc. radiator grille lower garnish	cracked	330.00	10	330.00	10
6pcs. radiator grille clips	necessary	24.00	10	24.00	10
1pc. radiator core support lower	refit	110.00	10	0.00	10
1pc. front bumper	dented	560.00	10	560.00	10
2pcs. bumper fog lamp LH & RH	refit	800.00	10	0.00	10
2pcs. bumper fog lamp cover LH & RH	complete with front bumper	240.00	10	0.00	10
1pc. bumper towing cover	dented/defaced	44.00	10	44.00	10
2pcs. bumper side bracket LH & RH	refit	100.00	10	0.00	10
1pc. bumper reinforcement	dented	800.00	10	614.00	10
1pc. bumper energy absorber	cracked	290.00	10	290.00	10
1pc. bumper lower apron bracket	broken/dislodged/missing	360.00	10	360.00	10
2pcs. front fender splash shield LH & RH	LH cracked	380.00	10	190.00	10
1pc. intercooler	dented	2,500.00	10	2,500.00	10
1pc. radiator assy	refit	1,100.00	10	0.00	10
1pc. radiator fan assy w/shroud	refit	900.00	10	0.00	10
1pc. drive shaft RH	refit	2,200.00	10	0.00	10
1pc. engine lower cover	cracked	370.00	10	370.00	10
SUPPLEMENTARY:-					
1pc. front air guide cover LH	cracked	130.00	10	130.00	10
1pc. front air guide cover RH	cracked	130.00	10	130.00	10
1pc. intercooler hose LH	cracked	700.00	10	550.00	10
Sub-Total :		12,528.00		6,092.00	
Total Discount :		1,252.80		609.20	
		11,275.20		5,482.80	
Special Nett :					
1pc. front emboss number plate with frame	dented	45.00		35.00	
5litres radiator coolant	necessary	50.00		35.00	
Sub-Total :		95.00		70.00	
Total Discount :		0.00		0.00	
		95.00		70.00	
Total For Parts :		11,370.20		5,552.80	


Vehicle No : GBH 6663 G Nissan NV200 (M)
Workshop : ASM Automotive Services Pte Ltd


IN-0003/04/21




Labour Charges :					
To remove and replace above damaged parts, realignment etc.		2,450.00		1,400.00	
To adjust and test drive wheel alignment system.		80.00		60.00	
Spray Painting Charges :					
Respray on affected areas and panels.		350.00		300.00	
Grand Total :		14,250.20		7,312.80	


Surveyor : LAWRENCE NG

























































RESURVEYED
REPAIRS



AFTER REPAIRS



AFTER REPAIRS



AFTER REPAIRS

