

(08/11/13) wef

ASS. REC. BY:

REF:

CS/EH/22012959/Rvg3

1706

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 1719G

at Workshop m/s MOVA

of Faw yoonh

Insured:

EHL

Policy No.

Claims No.

Sum Insured:


Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

108k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 1719G

Yr Regn: 2017 / OCT

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ GLA 180 4MATIC 1595

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

47825

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDC 1569422 J422573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/12/22

D.O.I.

30/12/22

Survey held at

MOVA

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/A

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Lim 11-68k

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) : S + RS : SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	0	Date of Loss:	23/12/2022
Vehicle Reg. No.:	SLT1719G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUA SIAK MONG		
Make/Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Vehicle Reg. Date:	20/10/2017
Vehicle Colour:	GREY	Chassis No:	WDC1569422J422573
Engine No:	27091031413113		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	11,310.93
Miscellaneous Items	0.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,840.93
+ GST 7.00% (\$\$)	898.87
Nett Amount (\$\$)	13,739.80

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT1719G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH <i>cm</i>	0.00	0.00	*3,765.00 F
2	1		*FRONT SUPPORT PANEL	0.00	0.00	*1,248.00 F
3	1		*FRONT SUPPORT PANEL BRACKET LH ?	0.00	0.00	*69.30 F
4	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*2,074.00 F
5	1		*FRONT BUMPER FINISHER COVER LH <i>ms</i>	0.00	0.00	*113.00 F
6	1		*FRONT BUMPER CLIPS <i>me</i>	0	0.00	*40.00 FS
7	1		*FRONT GRILLE ASSY	0.00	0.00	*392.00 F
8	1		*FRONT GRILLE BASE	0.00	0.00	*443.00 F
9	1		*FRONT BUMPER FINISHER BRACKET LH ?	0.00	0.00	*105.00 F
10	1		*FRONT FENDER LH <i>bt</i>	0.00	0.00	*1,350.00 F
11	1		*FRONT FENDER INNER LINER LH <i>cm</i>	0.00	0.00	*319.00 F
12	1		*FRONT FENDER EXTENSION COVER LH <i>de</i>	0.00	0.00	*368.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	10,286.30
+ Margin on L,N Items 10.00% (\$\$)	1,024.63
Total Parts (\$\$)	11,310.93

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REPLACE & REFIT FRONT RADIATOR, AIR COND CONDENSOR & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL	New	80? 100.00
2	TO REMOVE & REPLACE & REFIX & READJUST FRONT ACCIDENT AREA SUCH AS FRONT GRILLE, FRONT BUMPER, FRONT FENDER LH, FRONT HEADLAMP & ETC. BACK TO ORIGINAL CONDITION	New	400 500.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER & ETC	New	400.00
4	TO REFILL AIRCOND GAS & VACUUM	New	80? 100.00
5	TO REMOVE & REFIX FRONT BUMPER DISTANCE SENSOR, DISTANCE SENSOR RADAR & ETC. TO EFFECT REPLACE OF FRONT BUMPER	New	60 120.00
6	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	100 100.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	30 80.00
Gross Labour Cost (\$\$)			1,530.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasau

Hp 90010068

4 days

P/P

30/12/22 @ 1155

Excess: TBA

Revers

Resy before print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	170E
Vehicle Details	
Vehicle No.:	SLT1719G
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA180 URBAN (R18 LED)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	27091031413113
Chassis No.:	WDC1569422J422573
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,494.00
Original Registration Date:	20 Oct 2017
First Registration Date:	20 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$26,892.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2027
PARF Rebate Amount:	\$18,824.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$20,574.00
Total Rebate Amount:	\$39,398.00

Mercedes-Benz GLA-Class GLA180 Urban Edition

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price **\$108,688**

Depreciation **\$20,080 /yr**
[View models with similar depre](#)

Reg Date 10-Oct-2017
(4yrs 9mths 7days COE left)

Mileage 77,000 km (14.7k /yr)

Manufactured 2017

Road Tax \$740 /yr

Transmission Auto

Dereg Value \$38,555 as of today (change)

OMV \$27,747

COE \$42,900

ARF \$25,846

Engine Cap 1,595 cc

Power 90.0 kW (120 bhp)

Curb Weight 1,435 kg

No. of Owners 1