


# PRR ASSIGNMENT CS3/LPC22000769/Gtf3

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD  TP  N/S  TP RES  OD RES  EVA  INV  MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s Teck Siang Motor  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SY9311L Yr Regn: 12 Aug 2015  
 Type  M.Car  M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: MERCEDES BENZ C180 c.c 1595  
 Colour Silver A/C: Insured / Std / NI / NA  
 Sp.Reading 107437 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD2050402R083591 \*  
 Gen. Cond  Good  Fair / Poor / Burnt  
 Steering:  Inorder  Jammed / Leaked / Burnt or  
 Brake:  Inorder  Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/R or \_\_\_\_\_  
 Tyre Size: F: 225/50R17  
 R: //



(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

BS / DUN / EXNOVA  GY  FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

<u>Front</u>	<u>Rear</u>
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>24-01-2022</u>
Survey held at _____	<u>W/S</u> <u>1PM</u>

 Des. of Damages: Frt /  Rea  O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \$80k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	\$3000 - \$4000
<h2>submit PRR Report</h2>	

Date/Time, File Pass to?  : Preli. Report  : Final Report

1) \_\_\_\_\_

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  : Interview (\$ \_\_\_\_\_)  : Tech. Insp (\$ \_\_\_\_\_)  : Wash and (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + RS. SI \_\_\_\_\_

Photos \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL \_\_\_\_\_