

(1/3/11/13) wof

ASS. REC. BY: Paul

REF:

NS/INC22012970/Rqp3

821R

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SHD 4976S

Yr Regn: 2019 / 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI ELIONA 1.6 DCT

C.C. 1580

Colour

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

44893

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHC851424187441

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

155/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WESTLAK

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/12/22

D.O.I.

28/12/22

Survey held at

COMFLEX LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rasul finalised LS \$1400, 3 days. (Red \$1480.34, 51%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

TP

Lump Sum / L.B.H. (\$

1400

)

Date/Time: 28.12.2022 14:05

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5517991

JC NO.305541028


DMER S COMFORT TRANSPORTATION PTE LTD DMER NO. 7010045 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) UNIT CARD NO.	REGN NO.: SHD4976S MAKE: HYUNDAI MODEL: IONIQ(G3) YR OF MANU. 25.10.2019 CHASSIS CODE: KMHC851CVLU187441	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 28.12.2022 13:31 TARGET DATE COMPLETION DATE/TIME:
--	--	--

Accident Date: 22.12.2022
NATURE: 3P 22.12.2022

JOB DESCRIPTION

NO LABOR CODE
00010 PB

DESCRIPTION
LUMPSUM REPAIR-SHD4976S-TP



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHD4976S

LIMITS

Vehicle No.:

SHD4976S

REPAIR ESTIMATE

DATE: 28.12.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHD4976S

LKK-

INSURANCE: INCOME (L/S)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper <i>can</i>	1		\$ 459.40
	Rear Bumper Reinforcement ?	1		\$ 394.80
	Rear Bumper Reinforcement Brkt RH / LH ?	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding <i>de</i>	1		\$ 451.25
	Rear Bumper Lower Centre Moulding <i>at</i>	1		\$ 155.00
	Rear Bumper Under Centre Cover ?	1		\$ 225.00
	Rear Bumper Cover Clips <i>me</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper FogLamp X	1		\$ 201.50
	Rear Smart Key Antenna X	1		\$ 40.50
	SUB TOTAL			\$ 2,061.05
	LESS 20%			\$ 412.21
	DISCOUNTED TOTAL			\$ 1,648.84
	Reverse Sensor ?	1		\$ 180.00
	Rear No. Plate With Trim Cover <i>gan</i>	1		\$ 55.00 55
	S/NETT SUB			\$ 235.00
	LESS 10%			\$ 23.50
	S/NETT TOTAL			\$ 211.50
	Rear Fender Adv. Sticker RH / LH <i>me</i>	2	\$ 100.00	\$ 200.00 NETT
	SPARE PARTS TOTAL			\$ 2,060.34
	Labour Charge			
	Panel Beating			\$ 400.00 350
	Spray Painting Charge			\$ 300.00 250
	Remove/Refix Reverse Sensor			\$ 120.00 40
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 2,880.34

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign: _____

RASUL

Hp 90010068

3 days

L/S

28 ~~28~~ / 12 / 22 @ 1450

Repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/12/2022 16:10 (SGT)
Reported by	Driver
Date of Accident	22/12/2022 11:20 (SGT)
Exact Location of Accident	Ang Mo Kio Ave 5, Singapore
Additional Location Information	TOWARDS ANG MO KIO STREET 6
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4976S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	VXXXXXXX9138
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-93699218
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	NG YU CHUAN
NRIC No	SXXXX552J
Date Of Birth	13/10/1951
Occupation	Outdoor

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

28/02/1972
 50 YEARS AND 10 MONTHS
 Male
 (Phone) +65-93699218
 -
 fleetsafety@cdgtaxi.com.sg
 BLK 460 HOUGANG AVE 10 # 07 - 984
 -
 530460
 No
 Hirer
 No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
 Translator's name -
 Translator's ID -
 Translator's phone number -
 Translator's email -
 Original language used in the statement -

PASSENGER 1

Name UNKNOWN
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON 22.12.2022 AT ABOUT 1120HRS I WAS DRIVING MY VEHICLE A SHD4976S FETCHING MY PASSENGER TO ANG MO KIO STREET 6. MY VEHICLE A STOP ON THE 2ND LANE OF ANG MO KIO AVE 5 TRAFFIC JUNCTION OF ANG MO KIO AVE 6. VEHICLE B SKX360D THEN REAR ENDED MY STATIONARY VEHICLE A. MY PASSENGER IS NOT INJURED AND I PROCEEDED TO SEND HER TO DESTINATION AFTER TAKING SCENE PHOTOS AND HANDPHONE EXCHANGED. V

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident FILE IS NOT SUITABLE

Vehicle Registration Number	
Vehicle Manufacturer	SKX360D
Vehicle Model	Toyota
Vehicle Variant	Hiace
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Commercial vehicle
Contact Number	-
Address	(Phone) +65-84089427
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	FRONT
	-

IMPORTANT NOTICE

- ## 8. Consent under the Personal Data Protection Act (PDPA)

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLAMMABLE Reporting

Witnessed by Reporting Centre
Personnel 

The diagram shows a road layout on a grid. A car is positioned in the center lane, between two dashed lines. To the right of the car, there are two right-turn arrows. Above the car, the text 'ANG MO KIO AVE 5' is written. To the right of the entire road, the text 'ANG MO KIO AVE 6' is written vertically. On the far right, there is a large right-pointing arrow. On the left side, there are three right-pointing arrows. The road is bounded by solid lines on the left and right.

Describe Circumstances of the Accident

ON 22.12.2022 AT ABOUT 1120HRS I WAS DRIVING MY VEHICLE A SHD4976S FETCHING MY PASSENGER TO ANG MO KIO STREET 6. MY VEHICLE A STOP ON THE 2ND LANE OF ANG MO KIO AVE 5 TRAFFIC JUNCTION OF ANG MO KIO AVE 6. VEHICLE B SKX360D THEN REAR ENDED MY STATIONARY VEHICLE A.
MY PASSENGER IS NOT INJURED AND I PROCEEDED TO SEND HER TO DESTINATION AFTER TAKING SCENE PHOTOS AND HANDPHONE EXCHANGED.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

22.12.2022

1530HRS

Witnessed by Reporting Centre Personnel

FLASH ACCIDENT
REPORTING OFFICER
KYMI YONG



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHD4976S

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Dec 2022

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV FL 1.6 DCT

Primary Colour:

Blue

Manufacturing Year:

2019

Engine No.:

G4LELUR05087

Chassis No.:

KMHC851CVLU187441

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$25,501.00

Original Registration Date:

25 Oct 2019

First Registration Date:

25 Oct 2019

Transfer Count:

0

Actual ARF Paid:

\$12,702.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Oct 2027

PARF Rebate Amount:

\$9,526.00

Intended COE Rebate Details

COE Expiry Date:

24 Oct 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$24,460.00

COE Rebate Amount:

\$14,737.00

Total Rebate Amount:

\$24,263.00