#### **INSURER ENQUIRY**

# Find insurer

Vehicle reg. no.

smb1432r

#### **Date of Accident**

22/12/2022

Reset

#### % RESULT & RECEIPT

# TP Insurer Enquiry Insurance \_\_\_\_\_\_\_ MS First Capital Insurance Ltd Period of Insurance \_\_\_\_\_\_\_ 01/04/2022 - 31/03/2023 Requested By \_\_\_\_\_\_ Bonnie Kwok (Bonnie Kwok Llc) Requested Date \_\_\_\_\_\_ 28/12/2022 14:15

#### **Payment details**

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13** 

Total Amount Due (GST Inclusive): \$\$2

#### **General Insurance Association**

Records Management Centre GST Registration No: **M400017735** 

6S2Z22CN0802 / SNG AH TEE MOTOR & PANEL SERVICE PTE LTD ENTRY DATE & TIME. 23/12/2022 11:32 (SGT) SUBMITTED BY: JANICE CHANG VERSION: 1 (23/12/2022 11:32 (SGT))



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
   This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee: be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesed.

#### **ACCIDENT STATEMENT**

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

23/12/2022 11:32 (SGT) Driver 22/12/2022 11:40 (SGT) Eu Tong Sen St, Singapore twds 110 Lorong 23 Geylang Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

YN4002Z

INSUREDEPOLICAROLDER

Is company?

Name Of Registered Owner

Company Reg No

**Email Address** Mobile Phone No

Alternative Phone No.

SG SAGAWA AMEROID PTE LTD

1XXXXXX231D

SGSA-claim@sgh-global.com (Phone) +65-66029932

VEHICLE PARTICULARS

Model Variant Exact purpose for which vehicle was being used at time of

accident

Manufacturer

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

Mitsubishi Fe83be6srdea

No - Claiming third party Commercial vehicle

Manual 2977

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number MSIG Insurance (Singapore) Pte. Ltd. J400001453MKF

ORMER

Name of Driver Passport No/FIN Date Of Birth Occupation

YU XUELEI GXXXX883T 17/04/1982 Outdoor

Date Of Driving Pass Driving experience

Gender

Mobile Number

Alt. Phone Number Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT/S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Yes

No

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour Vehicle Category

Name of Driver

NRIC No

SMB1432R

23/12/2014

(Phone) +65-82662571

Collision - Head to Rear

SGSA-claim@sgh-global.com

BLK 230 TAMPINES ST 24 #08-126

8 YEARS

Male

524230

Employee

No

No

Clear

Dry

No

2

No

Yes

most.

No

No

No

MUHAMMED RISZUAN BIN ALI

SXXXX136B

Accident report SS2Z22CN0002

Page 2 of 18

#### IMPORTANT NOTICE


- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- $(v) \ complying \ w \ ith \ applicable \ law \ \ in \ administering, \ processing, \ handling \ and/or \ dealing \ w \ ith \ my \ claims.$

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Describe Circumstances of the Accident
On 22/12/2022 at about 11. 40am. I drove my
10rry 10 YN4002Z along Eu tong Sen street!
When I reached the place of En Tong Sen
street traffic light unction the traffic light
Was Amber lights change to red. So I responded by slowing down coming to stop
responded by slowing down coming to stop
Cafely at the traffic light function.
- Sixddenly the Big Bus behind Me with
Vehicle runber SMB1432R lit onto my
rear lorry 10 VN 4002 Z and Push my lorry
to move I forward to the dashed Pedestrions
crossing lines causing My lorry Rear body
Very dansafed
(No body in uned)

#### Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

1/83

14:46

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

# Constant Appraiser Services Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Mobile: 9007 5234
Email: constant\_as@yahoo.com.sg
RCB No. 53138015K

#### **INVOICE**

To: SG Sagawa Ameroid Pte Ltd

c/o 65 Chestnut Avenue

#18-15

Singapore 679524

Date

: 18/01/2023

Invoice No

: IV23-01015/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle YN 4002Z (Inclusive Of Photographs And Transport Charges)  Our reference: CAS/23-01/015	\$1,017.00
Total	\$1,017.00

E. & O.E

**Constant Appraiser Services** 

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Mobile: 9007 5234 Email: constant as@yahoo.com.sg RCB No. 53138015K

#### **Automobile Inspection Report**

To: SG Sagawa Ameroid Pte Ltd

c/o 65 Chestnut Avenue

#18-15

Singapore 679524

Date

: 18/01/2023

Reference No : CAS/23-01/015

#### **General Information**

Registration No. Accident Date

YN 4002Z 22/12/2022

#### Particulars of Damaged Vehicle

Colour

: Blue

Make & Model

: Mitsubishi FE83BE6SRDEA

**Engine Capacity** 

2977 cc

Pre-Accident Condition : Good

Mileage (KM)

399259

Engine No. Steering

: 4M42A91913

Chassis No. Registration Date : 21/08/2013

: FE83BEA21126

Brake

: In Order : In Order

#### **Tyre Condition**

Size

Make

Balance

R/H Front Tyre

7.00R16

LINGLONG

90%

L/H Front Tyre

7.00R16

LINGLONG

90%

R/H Rear Tyre L/H Rear Tyre

7.00R16 (D)

COPARTNER

60% / 60%

7.00R16 (D)

COPARTNER

60% / 60%

#### Inspection

Repairer

: LYS Engineering

65 Chestnut Avenue, #18-15, Singapore 679524

#### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate: \$19,932.26

Revised Amount

: \$13,700.00

Less Excess

Nett Total : \$13,700.00

#### Remarks

- (A) Survey was done on 22/12/2022
- (B) Re-survey was done on 05/01/2023
- (C) Re-survey after repair was done on 12/01/2023
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

#### **Constant Appraiser Services**

Vehicle No: YN 4002Z

Our ref: CAS/23-01/015

#### Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)		
		PARTS REPLACEMENT – LIST ITEMS					
1	lpc	Rear number plate lamp	Serviceable	71.20	-		
2	2pcs	Tail lamp assy @ \$285.10	Cracked/Broken	570.20	570.20		
				641.40	570.20		
		Less 10%		(64.14)	(57.02)		
			Sub total	577.26	513.18		
		PARTS REPLACEMENT – SPECIAL NETT ITEMS					
PATRICIA PARTICIPA PARTICI							
1	2pcs	Taillamp holder @ \$150.00	Dented/Twisted	300.00	300.00		
2	1 pc	Rear back door LH	Dented/Broken	1,800.00	1,800.00		
3	1pc	Rear back door hinge top LH	Bent/Twisted	450.00	450.00		
4	1pc	Rear back door hinge bottom LH	Bent/Twisted	450.00	450.00		
5	1pc	Rear back door inner lock bar with handle LH	Bent/Twisted	650.00	650.00		
6	1pc	Rear 60km/h sticker LH	Necessary	15.00	12.00		
7	1pc	Rear corporate advertisement	Necessary	800.00	600.00		
8	1pc	Rear back door RH	Dented/Warped	1,800.00	1,800.00		
9	1pc	Rear back door hinge top RH	Repair	450.00	-		
10	1pc	Rear back door hinge bottom RH	Repair	450.00	-		
11	1pc	Rear back door inner lock bar with handle RH	Bent/Twisted	650.00	650.00		
12	2pcs	Rooftop side rain rail @ \$250.00	Necessary	500.00	500.00		
13	1pc	Rooftop rear rain rail	Necessary	150.00	150.00		
14	1 pc	Rear step wooden member	Broken	500.00	500.00		
15	1pc	Rear end panel	Dented/Warped	850.00	850.00		
16	2pcs	Rear chassis top wooden cross member @ \$1,800.00	Broken	3,600.00	3,600.00		
17	2pcs	Rear chassis top wooden member end cover @ \$150.00	Dented	300.00	300.00		
18	2pcs	Rear cargo deck aluminum pillar @ \$950.00	N/S Dented	1,900.00	950.00		
19	2pcs	Rear rubber stopper @ \$180.00	Deformed/Broken	360.00	360.00		
20	1pc	Rear view camera	Damaged	450.00	320.00		
21	lset	Bolt & nut set	Bent/Necessary	150.00	120.00		
22	1pc	Rear number plate	Bent	40.00	40.00		
			Part total	17,192.26	14,915.18		
		<u> </u>					

#### **Constant Appraiser Services**

Vehicle No: YN 4002Z Our ref: CAS/23-01/015

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		LABOUR & MISC. CHARGES			
1		To check rear electrical wiring		40.00	20.00
2		Labour for panel beating, cut, weld, straighten & replacing parts etc		1,200.00	1,000.00
3		To putty & spray painting & including touch up paint on accident affected area		1,500.00	1,200.00
			Grand total	19,932.26	17,135.18
		t of lump sum repair t condition)			13,700.00

#### Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$13,700.00 on a contractual basis. Under normal circumstances, the repair period would be about 9 (Nine) working days.

Yours faithfully,

**Constant Appraiser Services** 

Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

**MSAAA** 

# **INVOICE**

Mailing Address:

Customer's Signature & Official Stamp

65 Chestnut Ave #18-15, Singapore 679524 Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695

## LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV

m/s_Sf	7 Sagawa Ameroid Pte YN 40022	No:	5249
 B Reg. 487541		Terms: C	01/2023
Quantity	Description	Unit Price \$ cts	Amount \$ cts
	lamp Sum repail	13,700. 00	13,700. 00
	within 30 days of date, interest at the st per month will be carry out until settled.	TOTAL	\$ 18.700. or
cheques should 'S ENGINEERIN	be crossed & made payable to	LYS ENGI	

E. & O. E.



MSIG Insurance (Singapore) Pte, Ltd.
4 Shepton Way, #21-01, 56X Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co Res No. 200412212G GST Reg. No. 20-0412212G
A Member of MSIVAD INSURANCE GROUP

#### CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 [MALAYSIA], ROAD TRANSPORT (AMENDMENT) ACT 2019 [MALAYSIA]

THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

## COMMERCIAL VEHICLE Comprehensive

Certificate No.

J 400001453 MKF

Excess: SGD2,000

Windscreen Excess: SGD100

- Index Mark and Registration Number of Vehicle YMARGAZ
- Name of Policyholder
   SG Sagawa Ameroid Pte Ltd
- Effective Date of the Commencement of Insurance for the purposes of the Act 01/04/2022
- Date of Expiry of Insurance 31/03/2023
- 5. Persons or Classes of Persons entitled to drive\*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use \*

Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. Use for social domestic and pleasure purposes. The Policy does not cover

- (1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- \* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 189) and Chapter 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offense under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Mark Eng



Enquire Vehicle Requisitestics: Details

Control of the Contro Carri Mari

Character & Charles

Committee

Same September

ST SACANNA AMERICAN PIR CIO

Continues in Carlottenine

TO PROMEEN WALK MEAN PRINCES OF MEM SHEESAFCHE SEPTES

Managery Adjustment

Side Core

Visitian an Paris

Contract Visitorias No.

Charles Control Chapter of

94 Age 3013

Chartestatistics

21 Aug 2011

Drogonal Burger (bilder Programmation (Summ

317003111

The Control of the Co

2012

Voltage of Types

Council (Council) (see Van Parel (Daken))

Visites his Signaporous

VALUE ASSESSMENT &

Veticle Althoroped I

versele filiale.

MTSLODISHI

Vehicle Medic

PERSONENSALSEA

Principly Control

\$400 mag

Security Course

ál.

Charles No.

FERSINEACTIN

Charles No.

44442491913

2077 cc/-

Management Control

Designation !

Lasten

Mary Christian White

AND KO

Magazinan Later New A

Saut va

Open Market Value

\$29.813 (8)

PARE CHORNE

No

DARK CITATION ENDING

Melenger PAHE BARNIN

No of Transitors

Reference West

13.000-100

COK NO.

COLUMN CAN

CONT. Calmings V

Company of the Action

Car Groots viendera bas

#### » Back to One Motoring

Vision to Change Particulars

#### Enquire PARF/COE Rebate for Registered Vehicle

		38466 348										
				(60)(60)								
		Carrier Carrier										

Vehicle Details

Vehicle No. YN4002Z

Volucie to be Exported

Intended Deregistration Date: 17 Mar 2022
Vehicle Mode: MITSUBISHI
Vehicle Mode: FX ISBESSRDEA

Princery Colour

Manufacturing Year

2013

Engine No. 4M42A91915

Chassis No. FEB36EA21126

Maximum Fower Output:

Open Market Value: \$29.813.00
Original Registration Date: 21 Aug 2013

First Registration Date: 21 Aug 2013

Transfer Count:

Actual ARF Paid: \$1,491.00

Intended PARF Rebate Details
PARF Eligibility
No

PARF Eligibility Expiry Date:

PARE Rebate Amount 50:00

Intended COE Rebate Details
20 Aug 2023

COE Expiry Date: 20 Aug 2023

C - Goods Vehicle & Bus

COEFerod Years)

CP Paid \$65,036.00 COE Repair Amount \$9,265.00

Total Rebate Amount. \$9,265.00

The information contained herein is correct as at 15 Mar 2022