

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AXA DATE 04/01/2023

ATTENTION : MOTOR CLAIMS DEPT JOB TYPE T/P CLAIM

ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SML6911P

MODEL : VOLKSWAGEN SHARAN 2.0

CHASSIS NO

ACCIDENT DETAILS DATE : 23-Dec-22
TIME : 20:50HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 1,855.30	\$ 1,855.30
2	REAR BUMPER (LOWER)	1	\$ 630.00	\$ 630.00
3	REAR BUMPER SIDE RETAINER LH	1	\$ 82.40	\$ 82.40
4	REAR BUMPER REFLECTOR LH	1	\$ 110.50	\$ 110.50
5	REAR BUMPER CENTRE FRAME	1	\$ 280.30	\$ 280.30
6	REAR BUMPER REINFORCEMENT	1	\$ 620.00	\$ 620.00
7	REAR BUMPER SENSOR	1	\$ 280.30	\$ 280.30
8	TAIL LAMP LH	1	\$ 622.40	\$ 622.40
9	REAR END PANEL	1	\$ 820.50	\$ 820.50

TOTAL PRICE \$ 5,301.70
LESS 10% \$ 530.17
SUB TOTAL PRICE \$ 4,771.53

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET)	1	\$ 20.00	\$ 20.00
2	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ 120.00

TOTAL \$ 140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	500	
3	TUFF COAT	\$ 250.00	X	
4	WIRING CHECK	\$ 80.00	50	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30	

TOTAL

\$2,810.00 1180

TOTAL PARTS COST : \$ 4,911.53
TOTAL LABOUR COS : \$ 2,810.00
TOTAL REPAIR COST : \$ 7,721.53

Total = 3418.77

20% = 683.75

= 2735.02

FT : ≈ 2750 //

APPROVED DETAILS
EXCESS :

PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

4/1/223

230pm 1rfm

L/S After painting

90097654

3 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: