(08/11/13) wef

ASS. REC. BY: [illegible]

REF: CS8/U012201 8001/RVY3

0844C

CUE - 2023/APR

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJE 5019U

at Workshop m/s AF & CARS

of 48, TOH GUAN RD #01-121

Insured: GBF 274X U01

Policy No.

Claims No. M11D00042301

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJE 5019U Yr Regn: 2008 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA VIOS E AUTO c.c 1497

Colour RED A/C: Insured / Std / NI / NA

Sp.Reading 203887 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY9305057140

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or DAVANTI

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 21/12/22 D.O.I. 30/12/22

Survey held at AF & CARS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 2.5K
	TOTAL LOSS
5/1/23	Submit ext T/L-mv: $4,000 (est) lta: $1234 nv:$2766

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 5/1/23-typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee: 380

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL 380