



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22007916/Dqy3e2-1	Date: 06/03/2023
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9810A	Veh. Inspected	SJN 957Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/026166	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	30/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN 200 SX	c.c	1809	
Engine No.	HIDDEN	Year of Reg.	1989	
Chassis No.	RS13500243	Colour	WHITE	
Odometer	191990 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35 R18	GOODYEAR	6 mm	
L/H Front Tyre	265/35 R18	GOODYEAR	6 mm	
R/H Rear Tyre	265/35 R18	GOODYEAR	6 mm	
L/H Rear Tyre	265/35 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2022	Inspection Date	19/08/2022	
Survey held at	Y2K AUDIO DESIGN 160 SIN MING DRIVE, #06-13, SIN MING AUTOCITY, SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	