

(08/11/13) wet

ASS. REC. BY: Marcus

REF:

CC4/ASM220/3025/4pa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBA 4108Tat Workshop m/s Enfuof SH 83238

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 06500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 2053Veh No: FBA 4108T Yr Regn: 21/04/06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

67200AMake: PIAGGIO VESPE c.c. 198Colour: Red A/C: Insured / Std / NI / NASp. Reading: 19362 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2APM3120000019209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120/70-12R: 130/70-12BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 03/11/22 D.O.I. 3/1/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 2402 APR 1 28-02-202613/1/23 L/S @ 2700 in front MR 700

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Liu Li Yuan Luxfer (85089688)

Accident Date : 03-Dec-22

Vehicle No : FBA4108T (COE280226)

Vehicle Model : Piaggio Vespa GT200A

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
1	Front fender <i>CU7</i>	\$ 230.00
1	Front fork assy <i>17</i>	\$ 980.00 <i>X</i>
1	Front shock absorber <i>17</i>	\$ 450.00 <i>X</i>
1	Top cover <i>2</i>	\$ 400.00 <i>X</i>
2	Front cowling mouldings <i>0/5 D/S</i>	\$ 140 280.00 <i>7C</i>
1	Side mirror (1 set) <i>Dupe</i>	\$ 200 450.00 <i>—</i>
1	Handle bar <i>su</i>	\$ 460.00 <i>X</i>
1	Hand grip set <i>17</i>	\$ 130.00 <i>X</i>
1	Handle bar balancer (1 set) <i>CU7</i>	\$ 50 120.00 <i>—</i>
1	Brake lever <i>CU7</i>	\$ 80.00 <i>—</i>
1	Exhaust assy <i>2</i>	\$ 850.00 <i>X</i>
1	Exhaust protector <i>CU7</i>	\$ 260.00 <i>—</i>
21	Rear side lower panels <i>0/5 CU7</i>	\$ 540.00 <i>—</i>
		\$ 5,230.00
Less 10%		\$ 523.00
		\$ 4,707.00
Special Net Items		
1	Number plate (1 set) <i>new</i>	\$ 38.00 <i>10</i>
1	Steering cone (1 set) <i>17</i>	\$ 180.00 <i>X</i>
1	Rear box <i>cra/Dupe</i>	\$ 750.00 <i>✓</i>
1	"VESPA" emblem <i>new</i>	\$ 100 180.00 <i>—</i>
		\$ 1,148.00
S/No.	Labour	
1	To provide towing service (LOD) \$50.00	\$ -
2	To check wiring and reset headlamp focusing	\$ 17 80.00 <i>X</i>
3	To provide labour	\$ 480.00 <i>400</i>
4	To repair body frame	\$ 550.00 <i>300</i>
5	To re-spray painting	\$ 1,200.00 <i>500</i>
		\$ 2,310.00
		\$ 8,165.00

Singapore Dollars: Eight Thousand One Hundred and Sixty-Five only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the Grand Total
- To display damaged parts for the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Page 1 of 1

Date:

P-1500
3410