

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|----------------|-------|---------------------|--|
| | EQ INSURANCE C | OMPANY LTD | | Ref: | CS/EQI22013036/Dvy3 | |
| | 5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSI | OCK | | Date: | 30/12/2022 | |
| | | | | Code: | EQI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SFD 1348Z | Veh. Inspected | | SNB 4580P | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | DM22HO02286 | Excess (\$) | | 0.00 | |
| | Assign From | NEO JIE SI | Assign Date | | 30/12/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer - Steering | | | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. Description of Damages | | | | | | |
| _ | | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 29/12/2022 | Inspection Dat | е | 30/12/2022 | |
| | Survey held at | | | | | |
| | | BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538 | | | | |
| 5a. | Sa. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |