

(08/11/13) Wef
ASS. REC. BY: P. Ann

REF: C83/MSH 23000032/Rqy3

4922


C08-2023/062

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJM 386A
at Workshop m/s GARAGE B P/L
of 1, BUCKS DRIVE CRESCENT WCCGA #05-55
Insured: MSH
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 11K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJM 386A Yr Regn: 2008 / 062
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: TOYOTA ISIS 1.8LXA c.c. 1794
Colour: BLUE A/C: Insured / Std / NI / NA
Sp. Reading: 190560 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZNM100054749
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 04/01/23
Survey held at GARAGE B
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Frt
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 8K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 4 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

: \$ + RS. \$ _____

: Interview (\$ _____)

: Photos

: Tech. Invs (\$ _____)

: Others

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	492Z

Vehicle Details

Vehicle No.:	SJM386A
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	ISIS 1.8LX A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1ZZ3105959
Chassis No.:	ZNM100054749
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,887.00
Original Registration Date:	18 Dec 2008
First Registration Date:	18 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$16,887.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$15,777.00
COE Rebate Amount:	\$2,994.00
Total Rebate Amount:	\$2,994.00

Toyota ISIS 1.8A LX (COE till 08/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$7,888

Depreciation 

\$12,680 /yr

Reg Date

21-Aug-2008
(7mths 15days COE left)

Mileage

180,000 km (12.5k /yr)

Manufactured 

2008

Road Tax 

\$1,458 /yr

Transmission

Auto

Dereg Value 

\$2,176 as of today (change)

OMV 

\$17,796

COE 

\$17,496

ARF 

\$13,328

Engine Cap

1,794 cc

Power

97.0 kW (130 bhp)

Curb Weight 

1,400 kg

No. of Owners 

2

Type of Vehicle

MPV