

ASS. REC. BY:

REF:

1CS/23 0000 531kw

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SBA 4K Yr Regn: 01, 17

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or Wagon

To Inspect Vehicle No: \_\_\_\_\_

Make: Toy Noah c.c. 1986

at Workshop m/s Topical

Colour: M. Brown A/C: Insured / Std / NI / NA

of \_\_\_\_\_

Sp. Reading: 60481 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: ZRR 80 0258021

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: \_\_\_\_\_

Mod: NII / S/Rlm / STBA Rlm or

(Policy Condition)

Tyre Size: F: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.



R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 890k

Front R/Bal. 8 mm Rear R/Bal. 8 mm

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

L/Bal. 8 mm L/Bal. 8 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

D.O.A. 27/12/22 D.O.I. 4/1/2023

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at \_\_\_\_\_

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: \_\_\_\_\_

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

Add Fee:  : Site Insp (\$)

Transportation

: Interview (\$)

S - RS, St

: Tech Invs (\$)

Fixes

: Weekend (\$)

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

Vertical text on the right edge: FRONT BUMPER PARKING SENSOR, PARKING SENSOR BRACKET, 20, 988.78, \$28.02, \$4.67, \$163.55, \$981.30

# Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL: 6481 7773 / 6481 1403 FAX: 6484 4978

E-mail: tsac303@singnet.com.sg

M/s: **ECICS Limited**  
10, Eunoss Road 8,  
Singapore Post Centre, #09-04A,  
Singapore 408600

Attn: Motor Claims Department  
Tel: 63374779  
Fax: 63389267

*Not withair*  
*11 Day @*  
*Penny After Pain*  
*5 days*

Estimate bill: TT 01 / 23 / TP / WT

Registration No: SBA4K

Make / model: Toyota Noah

Mileage:

Date: 03 / 01 / 2023

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SFC3188K AND SBA4K ALONG JUNCTION OF SENGKANG WEST WAY & FERVALE INK ON 27 DECEMBER 2022 AT ABOUT 2335HRS.**

2pcs	Rear windscreen moulding	(Each 81.00)	\$	<i>162.00</i>	✓
1pc	Rear boot		\$	<i>1,700.00</i>	✓
1pc	Rear boot rubber		\$	<i>351.00</i>	<i>509in</i>
1pc	Rear end panel top garnish		\$	<i>230.00</i>	✓
1pc	Rear wheel panel top cover		\$	<i>998.00</i>	X
1pc	Rear bumper		\$	<i>648.00</i>	✓
1pc	Rear bumper towing cover		\$	<i>33.00</i>	X
1pc	Rear bumper reflector (LH)		\$	<i>68.00</i>	X
2pcs	Rear bumper side retainer	(Each \$95.00)	\$	<i>190.00</i>	X
	Sub A total:		\$	4,380.00	
	Less 25% discount:		\$	1,095.00	
	A total:		\$	3,285.00	
<b>Special net items:</b>					
1set	Rear bumper parktronic sensor		\$	<i>200.00</i>	✓
	B total:		\$	200.00	
	Remove and refit rear windscreen.		\$	250.00	<i>1201</i>
	Remove and transfer rear boot necessary attachment part part items.				
	Remove and transfer rear bumper necessary attachment part part items.				
	Remove and refit rear boot, rear boot rubber, rear end panel top garnish, rear wheel panel top cover, rear bumper, rear bumper parktronic sensors, rear bumper towing cover, rear bumper reflector (LH), rear bumper side retainers.				
	Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.		\$	800.00	<i>6001</i>
	Diagnostic and reset rear bumper parktronic sensor fault error by HHT		\$	100.00	<i>501</i>
	Total amount of Page 3:		\$	4,635.00	

Tropical Tech Automobile Services

*(Handwritten Signature)*  
(Authorized Signature)  
William Tan



**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

s : **ECICS Limited**  
10, Eunus Road 8,  
Singapore Post Centre, #09-04A,  
Singapore 408600

Attn : **Motor Claims Department**  
Tel : 63374779  
Fax : 63389267

Estimate bill : TT 01 / 23 / TP / WT

Registration No : SBA4K

Make / model : Toyota Noah

Mileage :

Date : 03 / 01 / 2023

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SFC3188K AND SBA4K ALONG  
JUNCTION OF SENGKANG WEST WAY & FERVALE INK ON 27 DECEMBER 2022 AT ABOUT 2335HRS.**

To check and refit rear tail lamp wiring harness.	\$	80.00	201
Under coating on rear damaged portion.	\$	200.00	601
Putty / primer application, spray painting rear boot, rear bumper, rear bumper towing cover, rear bumper parktronic sensors.	\$	800.00	6601
Balance amount brought from Page 1 :	\$	4,635.00	
<b>Grand final amount :</b>	<b>\$</b>	<b>5,715.00</b>	

Tropical Tech Automobile Services

  
( Authorised Signature )  
William Tan



# SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**  
1. This form contains the details of the accident to speed up the claims process.  
2. This form must be completed by the Policyholder and/or the Actual Driver.  
3. The information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate the policy.  
4. The form and completion of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.  
5. This form may be referred to the Police for investigation.  
6. This report will be forwarded by the Insurer of the GIA Road & Management Centre established by the General Insurance Association of Singapore (GIA) for handling the claims of this report will, for a fee, be made available upon application by interested parties.  
7. By the submission of this report to the Insurers, you hereby consent to the surfacing of this report to the centre and to copies of the report being made available elsewhere.

## ACCIDENT STATEMENT

Date of Submission	28/12/2022 18:18 (SGT)
Reported by	Both
Date of Accident	27/12/2022 23:35 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION OF SENGKANG WEST WAY & FERNVALE LINK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBA4H
INSURED/POLICYHOLDER	
Is company?	No
Name of Registered Owner	TOH WEE PING
NRIC No	S1628877B
Email Address	kellytoh@live.com.sg
Mobile Phone No	(Phone) +65-90016916
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	NOAH 2.0X CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1988


## INSURANCE COMPANY

Name of Insurance Company	Longpac Insurance Sgd
Policy Number / Cover Note Number	222VP05630614

## DRIVER

Name of Driver	TOH WEE PING
NRIC No	S1628877B
Date Of Birth	21/06/1984
Occupation	Indoor

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Dec 2022 at 2335hrs, my car was stationary at the junction of Seugbang West Way and Fernvale Link waiting to turn into Fernvale Link. When the traffic lights turned green, I heard a loud bang from the back of my car. I turned around and saw a Mercedes had hit onto the back of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect

  
Police Officer's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

(AMK)  28/12/22  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No: