

(08/11/13)

wet

REF:

C8/FCI 23000056/Rvg³

ASS. REC. BY:

653M

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG 1889J

at Workshop m/s SBST

of 28,800N L66 RD

Insured: SBS 3399G FCI

Policy No.

Claims No. D23000006MFBP

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SG 1889J

Yr Regn:

2020 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN A22

C.C. 10518

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

118286

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMAA 22226JF008147

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22-5

R:

1 - 9/P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

22/12/22

D.O.I.

03/01/23

Survey held at

SBST

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/2/23

Final fig \$807.30 confirmed by email (Red 0)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2) 10/2/23-typist

Days Of Repair: 0.5

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) : S + RS \$

) : Photos

) : Others

Report Format : TP

Lump Sum / I.B.I.: (\$ 807.30

TOTAL

**BUS ENGINEERING
JR WORKSHOP**

SBS Transit

WORKSHOP REQUISITION

Bus Number: SG1889J
Order #: JR2212002509

Date: 22/12/2022
OrderType: JAC1

71M 22026005

S/No	Description Of Stock Item	Qty Indented
1	RH VIEW MIRROR cm	cm 30 400 005
2		
3		
4	TRASUL	
5	Hp 90010068	
6	1 day	
7	03/01/23 @ 1500	
8	Resu after	
9	reprv	
10		
11		
12	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	
13		
14		
15		
16		
17		
18		
19		
20		

Authorised By:

Name *Dang*

NRIC 111920

Designation *Y0*

Signature *[Signature]*

Indented By:

Name *CHOO HONG LIN*

NRIC 134385

Designation *TECH*

Signature *[Signature]*