

ASS. REC BY: Taufik

REF: 06/UP23000073/T243

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: \$110K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT EWIC

Veh No: SN A7787X Yr Regn: 2031 Oct. 2011 Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz SLK200 C.C. 1796

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 70652 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD1724482F-020184

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 5/1/23

Survey held at Auto Sprint

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

Taufikh finalised final fig \$900, 2 days. (Red \$100, 10%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 30/03 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.A. / 900

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. Sl. _____

Photos _____

Others _____

QUOTATION

To: Sany Kuek
SNA7787X, Mercedes Benz, SLK200

Our Ref : Q221212
Date : 29 Dec 2022

Attn : Sany Kuek (9100 6578)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SNA7787X against SLK7792B

No.	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
Ad hoc					
1	Labour Charge to panel beat r/h front fender.	1.00		200.00	200.00 ✓
2	Labour Charge to putty & respray painting on r/h front fender & front bumper assy. <i>Perk colour</i>	1.00		800.00	800.00 250 700
					\$900
					2 days #

Tanjin 97415749
5/1/23 @ 2:30pm
Resurvey after repair
Tanjin @ Khantow
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: 1,000.00
GST 7.0% : 70.00
Total Amount: 1,070.00