

CS/TMI23000090/Tqy3

ASS. REC BY: Taufik

REF:

TMI

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Suman

Vehicle: IN / OUT

Veh No: SHD665SE Yr Regn: 246, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220 C.C. 2143Colour: white A/C: Insured / Std / NI / NASp. Reading: 1087857 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD2120012K267937

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R16R: 225/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 3/1/23Survey held at Comfort Logon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$1850, 2 days. (Red \$1893, 51%)

Date/Time, File Pass 40?

1) 01/02 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format:

Lump Sum (Net) /

MER-TP

1850

Days Of Repair: 2Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

*Jumani  
Bin Masudin*

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/01/2023
Vehicle Reg. No.:	SHD6655E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ E220, 2.1 CDI (A)	Vehicle Reg. Date:	23/03/2016
Vehicle Colour:	WHITE	Gen Condition:	GOOD
Engine No:	65192433220474	Chassis No:	WDD2120012B307939
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

### COST OF CLAIMS

	Amount
Parts	2,732.00
Miscellaneous Items	11.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>3,743.00</b>
<b>+ GST 8.00% (\$\$)</b>	<b>299.44</b>
<b>Nett Amount (\$\$)</b>	<b>4,042.44</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System



**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2023)**Parts:** 143 MERCEDES-BENZ E220 2.1 CDI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD6655E/03/01/2023 14:37**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	Ry *1,510.00 FL
2	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *1,150.00 FL
3	1		*REAR BUMPER LOWER BRACKET LH	20.00	0.00	x *135.00 FL
4	1		*REAR BUMPER LOWER BRACKET RH	20.00	0.00	x *135.00 FL
5	1		*REVERSE SENSOR	0.00	0.00	cur *388.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,318.00</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>586.00</b>
<b>Total Parts (S\$)</b>	<b>2,732.00</b>

ComfortDelGro Engineering Pte Ltd/SHD6655E/03/01/2023 14:37. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

400

500.00

2 SPRAYPAINT

New

250

400.00

3 REMOVE/REFIX REVERSE SENSOR

New

30

100.00

Gross Labour Cost (\$\$)

1,000.00

ComfortDelGro Engineering Pte Ltd/SHD6655E/03/01/2023 14:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Tanpin 97495749  
 'WP' 3/1/22 @ 430pm  
 L/S rising after repair  
 Tanpin c / hhauto.com  
 @ 2 days

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

Date/Time: 03.01.2023 14:13

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5579300

JC NO.305541415

OWNER  
IS COMFORT TRANSPORTATION PTE LTD  
OWNER NO 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (R) (O)  
(P)

REGN NO SHD6655E	MILEAGE
MAKE MERCEDES BENZ	FUEL E.....1/2.....F
MODEL E220CDI (E6)	DATE/TIME IN 03.01.2023 12:00
YR OF MANU 23.03.2016	TARGET DATE
CHASSIS CODE WDD2120012B307939	COMPLETION DATE/TIME:


IDENT CARD NO.

JOB DESCRIPTION

Accident Date: 02.01.2023

ATURE: 3P.02.01.23

/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

No.: SHD6655E JU TOKIO

Vehicle No.: SHD6655E

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard