



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG23000092/Kwy3e2 Date: 27/04/2023 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FORKLIFT		Veh. Inspected	SKP 6364X
Policy No.			Coverage (\$)	0.00
Claim No.	297093		Excess (\$)	0.00
Assign From	ONG SHU XIANG		Assign Date	04/01/2023
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN PASSAT (A)		c.c	1798
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	WVWZZZ3CZEP008159		Colour	METALLIC DARK BLUE
Odometer	121977 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45Z R17	MICHELIN	8 mm	
L/H Front Tyre	235/45Z R17	MICHELIN	8 mm	
R/H Rear Tyre	235/45Z R17	MICHELIN	8 mm	
L/H Rear Tyre	235/45Z R17	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2022		Inspection Date	09/01/2023
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	