



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG23000092/Kwy3e2 Date: 09/05/2023 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FORKLIFT	Veh. Inspected	SKP 6364X
	Policy No.		Coverage (\$)	0.00
	Claim No.	297093	Excess (\$)	0.00
	Assign From	ONG SHU XIANG	Assign Date	04/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN PASSAT (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WWWZZZ3CZEP008159	Colour	METALLIC DARK BLUE
	Odometer	121977 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45Z R17	MICHELIN	8 mm
	L/H Front Tyre	235/45Z R17	MICHELIN	8 mm
	R/H Rear Tyre	235/45Z R17	MICHELIN	8 mm
	L/H Rear Tyre	235/45Z R17	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/12/2022	Inspection Date	09/01/2023
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	