

ASS. REC. BY:

REF: MSG / 2300682/KwKenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / XP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

10.30am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$ 41k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 6364X

Yr Regn:

09, 18Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Passat cc 1798

Colour:

M. D Blue

A/C: Insured / Std / NI / NA

Sp. Reading

121977

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZ88307EP008159Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

235/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

12

D.O.I.

9/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

cl/shock

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Wky unable to locate the parts for this model

Date/Time, File Pass to?



Prell. Report

1)

Date/Time, File Return to?



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Transportation

S - RS. \$

P. Ins

Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01, #04-02 &**  
**#07-03, Sin Ming Autocity**  
**575722**

**Insurer Reference: TP-Forlink (OMEX Pte Ltd)**  
**Repairer Reference: 73279**  
**Date calculated: 03/01/2023 9:33 AM**

**Full Report**  
**Registration: SKP 6364X**  
**Printed: 03/01/2023 9:33 AM**

### Summary Information

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-Forlink (OMEX Pte Ltd)	Date of Incident:	26/12/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

<b>Vehicle</b>			
Manufacturer:	VW		
Model:	PASSAT (3C)		
Sub Model:	HIGHLINE		
Model Sheet Number:	06 C2 03		
Registration:	SKP 6364X		
VIN number:	WVWZZZ3CZEP008159		
Odometer:			
<b>Model Specs</b>			
FROM 05.2013	LED NO PLATE LAMPS	PARK ASSISTANT	REARVIEW CAMERA
BUMPER COMFORT	CHROME PACKAGE	CLIMATRONIC	LED TAILLAMPS
RAIN SENSOR	KEYLESS ENTRY	DROWSINESS DETECTION	ELECT/FOLDING MIRROR
AUTO DIPPING MIRROR	8 SPEAKER	XENON HEADLAMPS	FOG LAMPS
HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT SWITCHING AUTO	WDW MOULDING CHROME
HEATED FRONT SEATS	DOOR TRIM IMIT LEATH	TRIM ALCANTARA	STRG WHEEL LEATHER
ELECT LUMBAR ADJUST	FRT ELECT MEM SEAT	ALTERNATOR 140A	1.8 LTR 118 KW
7-SPEED DSG	CRUISE CONTROL	TYRES 235/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	ALUMINIUM DECAL	HD COOLING	THROUGH LOAD SYSTEM
NAVIGATION SYSTEM	SALOON	ALUMINIUM DECAL	TWO COAT METALLIC
PREPARE OFF VEHICLE			

### Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
57 51 19 00	R + R RIGHT FRONT DOOR INCLUDES: ADJUST DOOR		3.0	15.00
57 51 55 50	RENEW RIGHT FRONT DOOR (DOOR REMOVED) INCLUDES: R + R ALL PARTS		22.0	110.00
58 51 19 00	R + R RIGHT REAR DOOR INCLUDES: DOOR ADJUST		3.0	15.00
58 51 55 50	RENEW RIGHT REAR DOOR (DOOR REMOVED) INCLUDES: R + R ALL PARTS		19.0	95.00



Labour Cost  
Panel / Mechanical Labour  
Total of Labour

Hrs 4.70 WU 47.0  
235.00  
235.00

## Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
	R/R DOOR NEW PART PAINTING	14.0	
	R/F DOOR COVER NEW PART PAINT K1R	3.0	
	R/R DOOR COVER NEW PART PAINT K1R	3.0	

## Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	41.80
1782	R/R DOOR NEW PART PAINTING	34.57
1688	R/F DOOR COVER NEW PART PAINT K1R	2.95
1988	R/R DOOR COVER NEW PART PAINT K1R	1.97

## Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			35.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
<b>Total</b>	<b>10 WU/h</b>	<b>6.50</b>	<b>65.0</b>	<b>325.00</b>

## Material Cost - Paint

	Price SGD
New Part Painting	76.37
New Part Painting - Plastic K1R	4.92
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>118.89</b>

## Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
1688	R/F DOOR COVER	3AA 854 940 A GRU			0.00
1510	R/F OUTER DOOR SEAL	3C4 837 702 D 5AP	Original	✓	165.00
1782	R/R DOOR	3AE 833 056	Original	✓	1,350.00
1988	R/R DOOR COVER	3AA 854 950 A GRU			0.00
1810	R/R OUTER DOOR SEAL	3C5 839 702 D 5AP	Original	✓	215.00
1482	RIGHT FRONT DOOR	3AA 831 056	Original	✓	1,350.00
<b>Savings</b>					<b>0.00</b>

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

Subtotal  
Addition(+10.00%)

3,080.00  
308.00

Total

3,388.00

### Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE AFTER REPAIR	80.00*
	<b>Total Extras</b>	<b>80.00</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>	3,080.00	
Addition(+10.00%)	308.00	
<b>Total Parts</b>		<b>3,388.00</b>
<b>Labour Time Base 10 WU/h</b>	235.00	
Total 47.0 WU X 50.00 SGD/h		<b>235.00</b>
<b>Total of Labour</b>		<b>80.00</b>
<b>Total Of Extras</b>		
<b>Paint Work Time Base 10 WU/h</b>	325.00	
Labour Cost 65.0 WU X 50.00 SGD/h	118.89	
Material Cost		<b>443.89</b>
<b>Total Paint Including Material</b>		<b>4,146.89</b>
<b>Repair Cost Excludes GST</b>		<b>331.75</b>
GST (+8.0%)		<b>4,478.64</b>
<b>Repair Cost Included GST</b>		

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

*Not within  
Mummy B4pam*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*4 days*



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	28/12/2022 12:00 (SGT)
Reported by	Both
Date of Accident	27/12/2022 14:00 (SGT)
Exact Location of Accident	Bukit Batok Street 24, Singapore
Additional Location Information	2 BUKIT BATOK 24 3RD FLOOR S659480 SINGAPORE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SKP6364X

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANGELA NG CHEE WAN (ANGELA WU ZHIYUN)
NRIC No	S7108745Z
Email Address	LOUISCHUNG.EBL@GMAIL.COM
Mobile Phone No	(Phone) +65-94502257
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Passat
Variant	VOLKSWAGEN / PASSAT 1.8 TSI AT 3624H7 HID
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1798

### INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10540013R01

### DRIVER

Name of Driver	CHUNG WEE JENG
NRIC No	S7005273C
Date Of Birth	16/02/1970
Occupation	Indoor

## IMPORTANT NOTICE

## SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
  - (ii) investigating the accident and/or my claims,
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

