

(08/11/13)

Wef

ASS. REC. BY: Tom

REF:

CC4/GRB23000121/Rpc3

7334

LOB-2025/DK

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 6703Jat Workshop m/s WAT HONGof 48, TOH KUAN RO BRST

Insured:

GRB

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

46K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 6703J

Yr Regn:

2015 / DK

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 3 SEDAN 1.6L SP3/R.c.c 1496

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

129074

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBM 42ABG0328558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

2.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

13/12/22

D.O.I.

01/01/23

Survey held at

WAT HONG

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 2/K

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS, SI

☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

):

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKX6703J MAZDA 3

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Headlamp RH ?		2358.00	
1	Grille top panel de-		352.00	
4	Grille top panel rivet@4*\$5 m		20.00	
4	Grille top panel clip@4*\$10 m		40.00	
1	Center grille cr		611.00	
2	Center grille inner side bracket RH/LH@2*\$17 ?		34.00	
1	Center grille logo badge m		47.00	
2	Center grille side lower chrome RH/LH@2*\$186 cr		372.00	
1	Front bumper de		1084.00	
2	Front bumper side retainer RH/LH@2*\$20 X		40.00	
2	Front bumper lower grille side garnish RH/LH@2*\$30 X		60.00	
1	Front reinforcement ?		594.00	
1	Front bumper sponge ?		98.00	
1	Boot lid logo badge m		80.00	
1	Boot lid emblem "Mazda 3" m		57.00	
1	Boot lid emblem "Skyactiv Technology" m		67.00	
1	Rear bumper de		1048.00	
2	Rear bumper side retainer RH/LH@2*\$38 X		76.00	
2	Rear bumper towing cover RH/LH@2*\$18 X		36.00	
2	Rear reverse sensor@2*\$204 ?		408.00	da rev?
1	Rear reinforcement ?		565.00	
1	Boot lid (Repair refer to labour)		0.00	
Part Items Total:			8047.00	
			-20% -1609.40	
			6437.60	
SPECIAL NETT ITEMS				
1	Front car plate X		35.00 X	
1	Front bumper clips m		35.00	
1	Center grille clips m		30.00	
1	Rear bumper clips m		35.00	
SN Items Total:			135.00	
Total Parts			6572.60	



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKX6703J MAZDA 3

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	200 X
4	To perform anti-rust treatment on affected areas	60.00	X
5	To remove, replace and focus headlamp	50.00	30
6	To remove and replace rear reverse sensor	100.00	40
Labour Total :		2300.00	
TOTAL (PARTS & LABOUR):		8872.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey
Apr 2001 to 68
5 days
L/S
09/01/23 @ 1420
Res after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 733G

Vehicle No.: SKX6703J

Vehicle to be Exported: No

Intended Deregistration Date: 10 Jan 2023

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP6EAT

Primary Colour: Grey

Manufacturing Year: 2015

Engine No.: P520337434

Chassis No.: JM6BM42A8G0328558

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$17,812.00

Original Registration Date: 22 Dec 2015

First Registration Date: 22 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$12,812.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Dec 2025

PARF Rebate Amount: \$7,687.00

COE Expiry Date: 21 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$57,301.00

COE Rebate Amount: \$16,882.00

Total Rebate Amount: \$24,569.00

The information contained herein is correct as at 10 Jan 2023

OK

Mazda 3 1.5A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$46,388

Depreciation ⓘ

\$13,920 /yr

[View models with similar depre](#)

Reg Date

31-Dec-2015

(2yrs 11mths 20days COE left)

Mileage

99,589 km (14.2k /yr)

Manufactured ⓘ

2015

Road Tax ⓘ

\$682 /yr

Transmission

Auto

Dereg Value ⓘ

\$22,959 as of today ([change](#))

OMV ⓘ

\$15,030

COE ⓘ

\$56,989

ARF ⓘ

\$10,030

Engine Cap

1,496 cc

Power

88.0 kW (118 bhp)

Curb Weight ⓘ

1,321 kg

No. of Owners ⓘ

2

Type of Vehicle

Mid-Sized Sedan