

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING)	APORE) PTE LTD	Ref:	CC4/ASM23000124/Apa3q2	
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	20/06/2023	
	ATTN:CYNTHIA		Code:	HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8762G	Veh. Inspected	GBJ 709M	
	Policy No.	P2465703	Coverage (\$)	0.00	
	Claim No.	S3M04HFM	Excess (\$)	0.00	
	Assign From		Assign Date	04/01/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	VSKYBAM20U0174413	Colour	WHITE	
	Odometer	112061 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
	L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
	R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
	L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/12/2022	Inspection Date	09/01/2023	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				