

ASS. REC. BY:

REF: 21

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

F - TMS

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road  
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg;samuelxie@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	20/12/2022
Vehicle Reg. No.:	<b>SKW8150X</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Vehicle Reg. Date:	18/11/2015
Vehicle Colour:	SILVER	Chassis No:	MR053REH104542717
Engine No:	1ZRY237591		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8 6		

*Not Whistle  
11/12/22  
Repair After Pain  
Ex TBA*

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS	Amount
Parts	5,017.05
Miscellaneous Items	111.00
Labour	2,280.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>7,408.05</b>
<b>+ GST 8.00% (S\$)</b>	<b>592.64</b>
<b>Nett Amount (S\$)</b>	<b>8,000.69</b>

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System



# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue: Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW8150X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	Ry 25.00	0.00	*1,498.40 FL ✓
2	1		*FRONT BONNET INSULATOR	Sm 25.00	0.00	*336.80 FL X
3	1		*FRONT BONNET LH HINGE	R 25.00	0.00	*70.80 FL X
4	1		*FRONT BONNET RH HINGE	Diy 25.00	0.00	*70.80 FL ✓
5	1		*FRONT BUMPER	CM 25.00	0.00	*639.80 FL ✓
6	1		*FRONT BUMPER RH RETAINER	CM 25.00	0.00	*102.60 FL ✓
7	1		*FRONT BUMPER UNDERCOVER	25.00	0.00	*117.80 FL ?
8	1		*FRONT RH FOGLAMP GARNISH	Sm 25.00	0.00	*105.60 FL X
9	1		*FRONT RH FOGLAMP	Sm 25.00	0.00	*394.10 FL X
10	1		*FRONT CHROME GRILLE	25.00	0.00	*204.20 FL ?
11	1		*FRONT RH FENDER	Ry 25.00	0.00	*1,091.50 FL ✓
12	1		*FRONT RH FENDER COWLING	CM 25.00	0.00	*251.60 FL ✓
13	1		*FRONT RH TOP SUPPORT PANEL	Ry 25.00	0.00	*1,364.40 FL ✓
14	1		*FRONT WIPER TANK	Nd 25.00	0.00	*263.00 FL ✓
15	1		*FRONT WIPER TANK NECK	Nd 25.00	0.00	*70.40 FL ✓
16	1		*FRONT REINFORCEMENT SPONGE	25.00	0.00	*107.60 FL ?

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,689.40</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>1,672.35</b>
<b>Total Parts (\$\$)</b>	<b>5,017.05</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	FRONT BUMPER CLIP	<i>Ne</i> 50.00 <i>—</i>
2	1	FRONT FRNDER COWLING CLIP	<i>Ne</i> 50.00 <i>—</i>
3	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			<u>111.00</u>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	<i>700</i> 1,200.00
2	To putty & respray on Front damage area.	New	<i>900</i> 1,000.00
3	To check wiring, focus headlamp.	New	<i>200</i> 80.00
Gross Labour Cost (S\$)			<u>2,280.00</u>

Report was unsubmitted during this print-out.  
 Generated using **Merimen e-Claims IEAS**  
**< END OF ESTIMATES >**



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	21/12/2022 10:28 (SGT)
Reported by	Driver
Date of Accident	20/12/2022 18:00 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	JURONG TOWN HALL ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8150X
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORTDELGRO RENT-A-CAR PTE LTD
Company Reg No	1XXXXX775H
Email Address	dannyng@cdgrentacar.com.sg
Mobile Phone No	(Phone) +65-97811517
Alternative Phone No	(Office) +65-68820888

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	ALTIS
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1598

#### INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D20MFL0000326_02

#### DRIVER

Name of Driver	MAENISHI YASHUHIRO
Passport No/FIN	GXXXX939P
Date Of Birth	12/06/1966
Occupation	Outdoor

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that :
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT  
REPORTING OFFICER

FRO KHAMARAJ




Policyholder's Signature / Date &amp; Time

Driver's Signature (If driver is not the policyholder) / Date &amp; Time

Witnessed by Reporting Centre Personnel

Sketch Plan

20/12/2022.- 20:20HRS



A- SKW8150X

B- GBB5937E



**- Back to OneMotoring**

## **Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars**

<b>Owner ID Type:</b>	<b>Company</b>
<b>Owner ID:</b>	<b>775H</b>
<b>Vehicle Details</b>	
<b>Vehicle No.:</b>	<b>SKW8150X</b>
<b>Vehicle to be Exported:</b>	<b>No</b>
<b>Intended Deregistration Date:</b>	<b>04 Jan 2023</b>
<b>Vehicle Make:</b>	<b>TOYOTA</b>
<b>Vehicle Model:</b>	<b>TOYOTA COROLLA ALTIS 1.6L CVT</b>
<b>Primary Colour:</b>	<b>Silver</b>
<b>Manufacturing Year:</b>	<b>2015</b>
<b>Engine No.:</b>	<b>1ZRY237591</b>
<b>Chassis No.:</b>	<b>MR053REH104542717</b>
<b>Maximum Power Output:</b>	<b>90.0 kW (120 bhp)</b>
<b>Open Market Value:</b>	<b>\$19,589.00</b>
<b>Original Registration Date:</b>	<b>18 Nov 2015</b>
<b>First Registration Date:</b>	<b>18 Nov 2015</b>
<b>Transfer Count:</b>	<b>0</b>
<b>Actual ARF Paid:</b>	<b>\$19,589.00</b>
<b>Intended PARF Rebate Details</b>	
<b>PARF Eligibility:</b>	<b>Yes</b>
<b>PARF Eligibility Expiry Date:</b>	<b>17 Nov 2025</b>
<b>PARF Rebate Amount:</b>	<b>\$11,753.00</b>
<b>Intended COE Rebate Details</b>	
<b>COE Expiry Date:</b>	<b>17 Nov 2025</b>
<b>COE Category:</b>	<b>A - Car up to 1600cc &amp; 97kW (130bhp)</b>
<b>COE Period(Years):</b>	<b>10</b>
<b>QP Paid:</b>	<b>\$57,301.00</b>
<b>COE Rebate Amount:</b>	<b>\$16,442.00</b>
<b>Total Rebate Amount:</b>	<b>\$28,195.00</b>

The information contained herein is correct as at 04 Jan 2023

**OK**