

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details				
Registration Number	SMB159L			
Case Reference Number	BUS/12/22/7013			
Registration Date	20/10/2011			
Company Type	SMRT Buses Ltd			
Make	MERCEDES			
Model	CITARO O530			
Name of Driver	Wang Wei			
Type of Accident	Side Swipe			
Accident Date and Time	19/12/2022 2:13 PM			
Accident Reported Date and Time	21/12/2022 10:58 AM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24117353			
Special Instruction to ARC,if any	SMB159L - RIGHT REAR PORTION SJE7640L (TP) - INSURED WITH INCOME			
Prepared Date and Time	3/1/2023 9:55 AM			
Chassis Number	WEB62808323122699			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	pair Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$1,060.00	\$530.00			
Total Spray Cost	\$786.00	\$616.00			
Total Spare Part Cost	\$0.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$1,846.00	\$1,146.00			
Lump Sum Total	\$1,850.00	\$0.00			
Number of Repair Days	3.0	2.0			
Prepared / Adjusted By	Kok Khoon Goh	Taufikh			
ARC / Surveyor Sign Off Date	03/01/2023 9:57 AM	04/01/2023 4:20 PM			
Signature	9	TOKKH			
Remarks					

	Section C - Quotation and	d Accident Invoice Details					
Quotation Number		Invoice Number					
Quotation Date		Invoice Date					
Invoice Amount		Prepared Date					

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 18/01/2023
User ID : CatherineLee



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 18/01/2023
User ID : CatherineLee

			Sect	tion D - Detail	s of Repair E	stimates			
Part 1 - Labou	ır Works								
Job Scope			Quotation from	Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR RH PORTION			\$1,060.00	\$1,060.00				\$530.00	
Total Labour			\$1,060.00				\$530.00		
Part 2 - Spray	Painting & Pa	anel Beating Rela	ted Works						
Job Scope		Quotation fro	Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00	\$786.00				\$616.00	
Total Spray Painting & Panel Beating			\$786.00	\$786.00			\$616.00		
Part 3 - Other	Costs - Accid	lent and Accident	Repair Related Exper	nse					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Mater	ial Usage		•					
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare	Parts / Materia	al Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									