

Date : 08/03/2023

MS First Capital Insurance Ltd

Attn: Motor Claims Department

Vehicle number : **SNH549B**
 Make and model : IONIQ ELECTRIC
 Registration Date : 23/09/2022
 Chassis number : KMHC851JUNU089876
 Engine number : EM10N5P0044J

Finalise

Job No. : 2023001824
 Owner name : KOMOCO CAR
 RENTALS PTE LTD
 Date of Acc : 21/12/2022
 Policy number : CN176488
 Claim Type : 3rd Party Claim

Items :		Estimate	Revise
1 BUMPER CLIP X10	86595-2T500	\$ 12.00	\$ 12.00
2 COVER-FR BUMPER	86511-G2500	\$ 452.40	\$ 481.10
3 MOULDING-FRONT BUMPER CTR,UPR	86585-G7500	\$ 138.30	Refix
4 MOULDING-FRONT BUMPER,RH	86564-G2550	\$ 93.00	\$ 93.00
5 LAMP ASSY-DAY RUNNING LIGHT,RH	92208-G2100	\$ 642.50	Refit
6 BRACKET-FR BUMPER SIDE SUPT,RH	86556-G2000	\$ 12.00	Refit
7 BRACKET-FR BUMPER SIDE,RH	86514-G2000	\$ 28.00	Refit
8 LAMP ASSY-HEAD,RH	92102-G2230	\$ 2,110.30	\$ 2,110.30
		\$ 3,488.50	\$ 2,696.40
Less 20% Discount		\$ 697.70	\$ 539.28
Material total		\$ 2,790.80	\$ 2,157.12

Body,Paint & Labour Items :	Estimate
1 To carry out accident body repair	\$ 840.00 \$ 420.00
2 Complete putty and spray paint all affected areas	\$ 760.00 \$ 510.00

Labour Charges:	Estimate
3 To supply & install Front number plate (S.NETT)	\$ 40.00 None

Total	\$ 4,430.80	\$ 3,087.12
Add GST 8%	\$ 354.46	\$ 246.97
Grand Total	\$ 4,785.26	\$ 3,334.09

*** Estimation are base on visual inspection, should there be furthur damages found
 during process of repair, you will be inform prior before carry out***