



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM23000200/Kqp3m4 Date: 27/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3670E	Veh. Inspected	SLR 9705D
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04GZZ	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	06/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZYX102015961	Colour	METALLIC GREY
	Odometer	421847 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	ARIVO	8 mm
	L/H Front Tyre	215/60 R17	ARIVO	8 mm
	R/H Rear Tyre	215/60 R17	ROADSTONE	7 mm
	L/H Rear Tyre	215/60 R17	ROADSTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/12/2022	Inspection Date	11/01/2023
	Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	