

(08/11/13) wef

ASS. REC. BY: John

REF:

CS/CT 23000218/RVP³

9439

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 918L

at Workshop m/s ETHOZ

of 30, BUCKLE BATHOR OREGENT

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 53K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 918L Yr Regn: 2018 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HILUX VAN TURBO 500 c.c. 2982

Colour: ORANGE A/C: Insured / Std / NI / NA

Sp. Reading: 284504 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02PX00233962

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Knock / Jammed / Leaked / Burnt or

Brake: Knock / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 75

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 03/12/22

Survey held at ETHOZ

Rear


R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 06/01/23

Des. of Damages: Frt / Rear / O/S (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

REPAIR LIMIT - 32K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519

FAX :

Date : 05/01/2023

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 03/12/2022

Vehicle No : GBH-918-L

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	SLIDING DOOR LH <i>bu</i>	980.00	
1	ROCKER PANEL LH	RESTORE	
1	REAR FENDER LH	RESTORE	

Sub Total 980.00

Discount 25% On Parts (245.00)

Special Nett Item

1	ADVERTISEMENT STICKER PANELS LH	1,000.00 <i>800</i>	
---	---------------------------------	--------------------------------	--

Date : 05/01/2023

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 03/12/2022

Vehicle No : GBH- 918-L

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1000.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	600.00 400	
	TO RESPRAY AFFECTED AREAS	600.00 500	
	TO REMOVE AND TRANSFER DOOR COMPONENTS	150.00 60	
	RUST PROOFING	50.00	
	Sub Total	1400.00	

3,135.00

Remarks:

4 days - L/s / Repair after repair

SUB TOTAL

GST 7.0 % 219.45

TOTAL 3,354.45

Surveyor's name:

Rasul - 4p 9006068

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

06/01/23 @ 1455

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE :

2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	943G
Vehicle Details	
Vehicle No.:	GBH918L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2752369
Chassis No.:	JTFHT02PX00233962
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	10 Jan 2018
First Registration Date:	10 Jan 2018
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jan 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$40,037.00
COE Rebate Amount:	\$20,040.00
Total Rebate Amount:	\$20,040.00