# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 29/12/2022 15:58 (SGT) Reported by Driver Date of Accident 29/12/2022 11:10 (SGT) Exact Location of Accident 290 Orchard Rd, Singapore 238859 Additional Location Information PARAGON MALL Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number **GBK802X** 

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner **GOLDBELL LEASING PTE LTD** Company Reg No 1XXXXX196N Email Address isaacngcl@gbl.com.sg Mobile Phone No (Phone) +65-85143130 Alternative Phone No (Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer Mitsubishi Model Canter Variant Exact purpose for which vehicle was being used at time of

accident **Employment** Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Commercial vehicle Transmission Manual CC 2998

**INSURANCE COMPANY** 

Name of Insurance Company MS First Capital Insurance Ltd Policy Number / Cover Note Number D22099240

DRIVER

Name of Driver HERRUDI BIN SALIM NRIC No SXXXX231B Date Of Birth 09/04/1981 Occupation Outdoor

Date Of Driving Pass 19/05/2003 Driving experience 19 YEARS AND 7 MONTHS Gender Mobile Number (Phone) +65-85143130 Alt. Phone Number Email Address isaacngcl@gbl.com.sg Address BLK 551 JURONG WEST STREET 42 #06-255 Address complement Postcode 640551 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON THE 29/12/2022 AT ABOUT 1110 HOURS, I WAS DRIVING VEHICLE A (GBK802X) IN STATIONARY POSITION INSIDE A LOADING BAY LOT WITHIN PARAGON MALL WHEN VEHICLE B (YM4940X) WAS EXECUTING A REVERSE INTO A LOT ON MY WARN HIM WHEN HE IS ALREADY VERY CLOSE TO ME BUT HE STILL CONTINUED TO REVERSE. NOBODY IS INJURED.

LEFT BUT HIS REAR RIGHT HIT THE LEFTSIDE PORTION OF MY TRUCK. I HAVE ALREADY SOUNDED MY HORN TWICE TO

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number YM4940X Vehicle Manufacturer Mitsubishi Vehicle Model Fe85pg6srde Vehicle Variant Vehicle Colour

Vehicle Category Commercial vehicle



Name of Driver	HU WEIXU
Work Permit No	GXXXX889X
Contact Number	(Phone) +65-91387456
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

#### SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

Lunderstand, acknowledge, agree and consent that :


- (a) My Insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of;
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing w ith my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 29/12/22 1300

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON THE 29/12/2022 AT ABOUT 1110 HOURS, I WAS DRIVING VEHICLE A (GBK802X) IN STATIONARY POSITION INSIDE A LOADING BAY LOT WITHIN PARAGON MALL WHEN VEHICLE B (YM4940X) WAS EXECUTING A REVERSE INTO A LOT ON MY LEFT BUT HIS REAR RIGHT HIT THE LEFTSIDE PORTION OF MY TRUCK. I HAVE ALREADY SOUNDED MY HORN TWICE TO WARN HIM WHEN HE IS ALREADY VERY CLOSE TO ME BUT HE STILL CONTINUED TO REVERSE. NOBODY IS INJURED.	-	
		(GBK802X) IN STATIONARY POSITION INSIDE A LOADING BAY LOT WITHIN PARAGON MALL WHEN VEHICLE B (YM4940X) WAS EXECUTING A REVERSE INTO A LOT ON MY LEFT BUT HIS REAR RIGHT HIT THE LEFTSIDE PORTION OF MY TRUCK. I HAVE ALREADY SOUNDED MY HORN TWICE TO WARN HIM WHEN HE IS ALREADY VERY CLOSE TO ME BUT HE STILL CONTINUED TO REVERSE.

# Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date & Time 29 | 12 | 22 | 1300

Personnel

Witnessed & Reporting Centre













