

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURA	NCE PTE LTD		Ref:	CS/LIP23000239/Uwy3m4	
	51 CLUB STREET, LIBERTY HOUSES	#03-00 SINGAPORE 069428		Date:	25/01/2023	
				Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SCH 3233Y	Veh. Inspected	l	SNE 8164R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	IVS23/0070	Excess (\$)		0.00	
	Assign From	ANDY SEAH	Assign Date		09/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	RENAULT GRAND SCENIC(A)	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	VF1RFA00363211887	Colour		BEIGE	
	Odometer	13946 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R20	GOODYEAR		7 mm	
	L/H Front Tyre	195/55 R20	GOODYEAR		7 mm	
	R/H Rear Tyre	195/55 R20	GOODYEAR		7 mm	
	L/H Rear Tyre	195/55 R20	GOODYEAR		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/01/2023	Inspection Dat	е	09/01/2023	
	Survey held at	CARSMITH PTE LTD				
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807				
5a.	Remarks					
	A)REGISTRATION DATE: 12 APR 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	STIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				