

ASS. REC. BY:

REF:

CIP / 23000240/kw

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

05/04/2023 Finalise L/S \$5,200.00 @ 07 days (Red \$4,999.30/49%)

MV- \$53,000 LTA- \$28,925 NV- \$24,075

Date/Time, File Pass to?

05/04/2023

1) typist

Date/Time, File Return to?



: Prel. Report



: Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Survey Fee:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Transportation

S - RS. SI

: P. Ins

: Other

Report Format: TP

Lump Sum / I.B.I. (\$) L/S. \$5,200

Veh No:

SNE 5333P

Yr Regn:

06, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Veeol

c.c

148

Colour

M. R. White

A/C:

Insured / Std / NI / NA

Sp. Reading

191015

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AU 1

1118948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inopder / Jammed / Leaked / Burnt or

Brake: Inopder / Jammed / Leaked / Burnt or

Modl: NII / SI/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/55R17

70yo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

4/1/23

D.O.I.

9/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.