

LM L15

TOTAL

	N/S	O/S	

Front Rear
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. 3 mm L/Bal. 3 mm
 D.O.A. 10/12/2022 D.O.I. 12/12/2022
 Survey held at COFF LOYANG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
___ S + RS ___ SI	
Photos	
Others	
TOTAL	