

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2300435

INV Date 19/01/2023

Reference CS/EQI23000299/Kqy3m4

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SJM 2959J

Insured Veh. GBG 4785G

Claim No. DM23HO00045/JT

Policy No. DMCPHQ22-002404

Accident Date 05/01/2023

Inspection Date 10/01/2023

| Description | Total |
|---------------------|--------|
| Survey Inspection | 160.00 |
| Resurvey Inspection | |
| Digital Photographs | |
| Transportation | |
| Subtotal | 160.00 |
| GST (8%) | 12.80 |
| Grand Total | 172.80 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| | | Affiliated to Federation Internation | nale Des Experts En Automo | bile |
|----|--|---|--|---------------------------|
| | EQ INSURANCE C | OMPANY LTD | Ref: | CS/EQI23000299/Kqy3m4 |
| | 5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI | | Date: | 19/01/2023 |
| | | | Code: | EQI |
| 1. | | Policy Particulars | :- THIRD PARTY CLAIN | 1 |
| | Insured Veh. | GBG 4785G | Veh. Inspected | SJM 2959J |
| | Policy No. | DMCPHQ22-002404 | Coverage (\$) | 0.00 |
| | Claim No. | DM23HO00045/JT | Excess (\$) | 0.00 |
| | Assign From | NEO JIE SI | Assign Date | 09/01/2023 |
| 2. | | Vehicle Partic | culars & Condition | |
| | Make & Model | HYUNDAI AVANTE S (A) | c.c | 1591 |
| | Engine No. | HIDDEN | Year of Reg. | 2008 |
| | Chassis No. | KMHDU41BR9U647362 | Colour | METALLIC GREY |
| | Odometer | 345699 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. | | Condition | ons of Tyres | |
| | | Size | Make | Balance |
| 1 | | 00E/EE D40 | TRIANGLE | 8 mm |
| | R/H Front Tyre | 205/55 R16 | TRIANGLE | 9 111111 |
| | R/H Front Tyre L/H Front Tyre | 205/55 R16 205/55 R16 | TRIANGLE | 8 mm |
| | | | | |
| | L/H Front Tyre | 205/55 R16 | TRIANGLE | 8 mm |
| 4. | L/H Front Tyre R/H Rear Tyre | 205/55 R16 205/55 R16 205/55 R16 | TRIANGLE BRIDGESTONE | 8 mm 6 mm |
| 4. | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre | 205/55 R16 205/55 R16 205/55 R16 | TRIANGLE BRIDGESTONE BRIDGESTONE on of Damages | 8 mm 6 mm |
| 4. | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REA | TRIANGLE BRIDGESTONE BRIDGESTONE on of Damages | 8 mm 6 mm |
| 4. | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REALES. | TRIANGLE BRIDGESTONE BRIDGESTONE on of Damages | 8 mm 6 mm |
| | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REALES. | TRIANGLE BRIDGESTONE BRIDGESTONE on of Damages AR & FRONT PORTION. | 8 mm 6 mm |
| | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REALETAILS. General | TRIANGLE BRIDGESTONE BRIDGESTONE on of Damages AR & FRONT PORTION. | 8 mm 6 mm 6 mm |
| | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REALETAILS. General 05/01/2023 | TRIANGLE BRIDGESTONE BRIDGESTONE On of Damages AR & FRONT PORTION. Information Inspection Date | 8 mm 6 mm 6 mm |
| | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General 05/01/2023 EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 | TRIANGLE BRIDGESTONE BRIDGESTONE On of Damages AR & FRONT PORTION. Information Inspection Date | 8 mm 6 mm 6 mm |
| 5. | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date Survey held at | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General 05/01/2023 EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 | TRIANGLE BRIDGESTONE BRIDGESTONE On of Damages AR & FRONT PORTION. Information Inspection Date Emarks HOUT PREJUDICE" BASIS | 8 mm 6 mm 6 mm 10/01/2023 |
| 5. | L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date Survey held at | 205/55 R16 205/55 R16 205/55 R16 Description STAINED DAMAGES AT THE REAL SETAILS. General 05/01/2023 EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 Real SON WAS CONDUCTED ON A"WIT DE TO YOUR INSTRUCTIONS, W | TRIANGLE BRIDGESTONE BRIDGESTONE On of Damages AR & FRONT PORTION. Information Inspection Date Emarks HOUT PREJUDICE" BASIS | 8 mm 6 mm 6 mm 10/01/2023 |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 2959J

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRT BUMPER | CRACKED | 574.50 | 494.40 |
| 2 | FRT BUMPER SIDE HOLDER L/R @\$36.20 | SERVICEABLE | 72.40 | - |
| 1 | FRT GRILLE | CRACKED | 352.20 | 352.20 |
| 1 | FRT BUMPER LOWER GRILLE | SERVICEABLE | 124.50 | - |
| 1 | FRT BUMPER INNER FOAM | CRACKED | 162.60 | 162.60 |
| 1 | FRT BUMPER REINFORCEMENT | BENT | 282.60 | 282.60 |
| 1 | FRT SUPPORT PANEL | CRACKED | 783.20 | 783.20 |
| 2 | HEADLAMP L/R @\$594.20 | MTG CRACKED | 1,188.40 | 1,100.00 |
| 1 | REAR BOOT LID | BENT | 886.00 | 886.00 |
| 2 | REAR BOOT LID REFLECTOR LAMP L/R @\$126.20 | SERVICEABLE | 252.40 | - |
| 1 | REAR BOOT LID OUTER MOULDING | WARPED | 136.50 | 136.50 |
| 1 | REAR BOOT LID ADVANTE EMBLEM | NECESSARY | 32.50 | 32.50 |
| 1 | REAR BOOT LID S EMBLEM | NECESSARY | 25.60 | 25.60 |
| 1 | REAR BOOT LID HYUNDAI LOGO | NECESSARY | 32.90 | 32.90 |
| 1 | REAR BOOT LID MECHANISM LOCK | DENTED | 168.00 | 168.00 |
| 1 | REAR BOOT LID INNER UPHOLSTRY TRIM | SERVICEABLE | 126.40 | - |
| 2 | REAR BOOT LID HINGES L/R @\$112.70 | TO REPAIR SEE LABOUR | 225.40 | - |
| 1 | REAR BUMPER | BUCKLED | 582.20 | 489.00 |
| 2 | REAR BUMPER SIDE HOLDER L/R @\$42.30 | SERVICEABLE | 84.60 | - |
| 1 | REAR BUMPER REINFORCEMENT | CRACKED | 286.20 | 286.20 |
| 2 | REAR BUMPER BRACKET L/R @\$78.30 | N/S BENT | 156.60 | 78.30 |
| 1 | REAR BUMPER INNER FOAM | CRACKED | 141.40 | 108.20 |
| 1 | REAR END PANEL | BENT | 485.10 | 485.10 |
| 1 | REAR END PANEL TOP GARNISH | DENTED | 89.30 | 89.30 |
| 2 | REAR LAMP L/R @\$326.20 | O/S CRACKED | 652.40 | 326.20 |
| | LESS 20% DISCOUNT | | -1,580.78 | -1,263.76 |
| | | | 6,323.12 | 5,055.04 |
| 1 | REAR BOOT WEATHERSTRIP (50%) (SN) | DENTED/ DISTORTED | 118.50 | 59.25 |

Report Ref No. CS/EQI23000299/Kqy3m4



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------|----------------------------|-------------------|
| | LESS 20% DISCOUNT | | -23.70 | - |
| | | | 94.80 | 59.25 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRT LICENSE PLATE (SN) | BENT | 50.00 | 45.00 |
| 1 | REAR LICENSE PLATE (SN) | SERVICEABLE | 50.00 | - |
| 1 | SET FRT BUMPER CLIP (SN) | NECESSARY | 45.00 | 45.00 |
| 1 | SET FRT GRILLE CLIP (SN) | NECESSARY | 35.00 | 35.00 |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 45.00 | 45.00 |
| 1 | SET END PANEL GARNISH CLIP (SN) | NECESSARY | 35.00 | 35.00 |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 250.00 | 200.00 |
| | | | 510.00 | 405.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS. | | 100.00 | 40.00 |
| | TO REMOVE & REPLACE UPHOLSTRY, TRIM GARNISHES TO FACILITATE REPAIRS. | | 100.00 | 60.00 |
| | TO REMOVE & TRANSFER BOOT LID COMPONENTS. | | 80.00 | 50.00 |
| | TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGES L/R. | | 1,000.00 | 800.00 |
| | PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS. | | 1,200.00 | 800.00 |
| | TO REMOVE & RENEW REVERSE SENSOR. | | 100.00 | 50.00 |
| | RUST PROOFING ON AFFECTED PORTIONS. | | 100.00 | 60.00 |
| | | | 2,680.00 | 1,860.00 |
| | GRAND TOTAL | | 9,607.92 | 7,379.29 |
| | DECOMMENDED COST OF LUMP SUM DEPAIRS | | | 5 000 00 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 5,900.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CS/EQI23000299/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/01/2023 11:15 (SGT) Reported by Date of Accident 05/01/2023 14:06 (SGT) Exact Location of Accident Singapore Additional Location Information CTE (TOWN BEFORE BALESTIER EXIT) Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJM2959J

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner ASSET LIMO Company Reg No 53309913K Email Address jamesleecars@hotmail.com Mobile Phone No (Phone) +65-90218889 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Hyundai Model HD AVANTE 1.6 A Variant Exact purpose for which vehicle was being used at time of

accident Private use Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 1591

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd Policy Number / Cover Note Number P2382948

DRIVER

Name of Driver SIVAKUMAR S/O VIJAYA KUMAR NRIC No S7628037A Date Of Birth 14/09/1976 Occupation Outdoor

Date Of Driving Pass 24/07/2015 Driving experience 7 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-93492434 Alt. Phone Number Email Address jamesleecars@hotmail.com Address BLK 134 YISHUN STREET 11 #08-167 Address complement Postcode 760134 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number GBG4785G Vehicle Manufacturer Toyota

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

NRIC No

GBG4785G

Toyota

Dyna

Private

FAIROS KHAN BIN AMIR KHAN

S8117323J



| Contact Number Address | (Phone) +65-87545179 |
|---|----------------------|
| Address complement | - |
| Postcode | _ |
| Insurance Company Name | _ |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

DETAILS OF OTHER VEHICLE PROPERTY 2

| Vehicle Registration Number Vehicle Manufacturer Vehicle Model | SMG5631E Kia Cerato |
|--|---------------------------|
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | CHIA CHEW CHUA |
| NRIC No | S1042488G |
| Contact Number | (Phone) +65-81125198 |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

King

Sketch Plan

CTE > Bt. Timah

B) GBG 4785 G C) SMG 5631E

 \rightarrow

BUADOCA

| Describe Circumstances of the Accident |
|---|
| when the Vehicle in front of mine braked. |
| I braked as well. Subsequently about 5 seconds |
| later I felt an impact from the rear of car, |
| pushing my can forward & collided onto the |
| thank Vehicle. I was alighted to sheek & realised |
| I braked as well. Subsequently about 5 seconds later I felt an impact from the rear of car, pushing my car forward & collided onto the front Vehicle. I was alighted to check & realised Veh (B) had rear-ended my car causing the 3-cars |
| chair collision. |
| Chain collision. We exchange posticullors & left the scene. No one was injured. |
| no one was injured |
| |
| |
| Claiming TP at EM Solution Pte Ltd. |
| 7 |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Personnel



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 2959J


INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 2959J

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 2959J

RE-INSPECTION







