

ASS. REC. BY:

REF:

EQ / 23 0002991k Xqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GBG 4785G

Policy No.

Claims No. DM23HO00045/JT

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

847K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STM 2959J

Yr Regn:

12, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante 1.591

Colour

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

343 899

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM40U41BR-94647362

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Hank

R: B.S. 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

6

mm

D.O.A.

8/1/23

D.O.I.

10/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1/23 11:00 859000 Cuhw

(red 3707.92, 38%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / t.B.t. (\$ 5900)

2) 18/1/23-typist

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 913K

Vehicle Details

Vehicle No.: SJM2959J
Vehicle to be Exported: No
Intended Deregistration Date: 09 Jan 2023
Vehicle Make: HYUNDAI
Vehicle Model: HD AVANTE 1.6 A
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: G4FC8U565312
Chassis No.: KMH DU41BR9U647362
Maximum Power Output: 89.7 kW (120 bhp)
Open Market Value: \$11,726.00
Original Registration Date: 27 Dec 2008
First Registration Date: 27 Dec 2008
Transfer Count: 2
Actual ARF Paid: \$11,726.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Dec 2028
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$27,571.00
COE Rebate Amount: \$16,438.00
Total Rebate Amount: \$16,438.00

The information contained herein is correct as at 06 Jan 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/01/2023 11:15 (SGT)
Reported by	Driver
Date of Accident	05/01/2023 14:06 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE (TOWN BEFORE BALESTIER EXIT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM2959J
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	ASSET LIMO
Company Reg No	53309913K
Email Address	jamesleecars@hotmail.com
Mobile Phone No	(Phone) +65-90218889
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	HD AVANTE 1.6 A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	P2382948

DRIVER

Name of Driver	SIVAKUMAR S/O VIJAYA KUMAR
NRIC No	S7628037A
Date Of Birth	14/09/1976
Occupation	Outdoor

Date Of Driving Pass	24/07/2015
Driving experience	7 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93492434
Alt. Phone Number	-
Email Address	jamesleecars@hotmail.com
Address	BLK 134 YISHUN STREET 11 #08-167
Address complement	-
Postcode	760134
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG4785G
Vehicle Manufacturer	Toyota
Vehicle Model	Dyna
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	FAIROS KHAN BIN AMIR KHAN
NRIC No	S8117323J

Contact Number	(Phone) +65-87545179
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG5631E
Vehicle Manufacturer	Kia
Vehicle Model	Cerato
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHIA CHEW CHUA
NRIC No	S1042488G
Contact Number	(Phone) +65-81125198
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Describe Circumstances of the Accident

When the vehicle in front of mine braked,
I braked as well. Subsequently about 5 seconds
later, I felt an impact from the rear of car,
pushing my car forward & collided onto the
front vehicle. I was alighted to check & realised
Veh (B) had rear-ended my car causing the 3-cars
chain collision.
We exchange particulars & left the scene.
No one was injured.

claiming TP at EM Solution Pte Ltd.

Declaration

I/We declare the foregoing particulars are true in every respect.





Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time


Kiara



Witnessed by Reporting Centre
Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

W
ASSET LIMO

Policyholder's Signature / Date & Time


[Signature]


Driver's Signature (If driver is not the policyholder) / Date & Time

Kina

Witnessed by Reporting Centre Personnel

Sketch Plan









EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*Not known
11 By @ 5300/hr
Presony After Rain
- 6 days*

ESTIMATE

Date : 7th January 2023

M/s **Asset Limo**
18 Sin Ming Lane #07-37
Singapore 573960

Veh No : **SJM 2959J**
Make/Model : **Hyundai Avante**
Chassis No : KMHDU41BR9U647362
Date of Acc : 05.01.23
TP Veh No : GBG 4785G

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Bumper <i>494.40</i>		\$ CM 574.50 ✓
2	2 pcs	Frt Bumper Side Holder L/R	\$ 36.20	\$ Pm 72.40 X
3	1 pc	Frt Grille		\$ CM 352.20 ✓
4	1 pc	Frt Bumper Lower Grille		\$ Pm 124.50 X
5	1 pc	Frt Bumper Inner Foam		\$ CM 162.60 ✓
6	1 pc	Frt Bumper Reinforcement		\$ Pm 282.60 ✓
7	1 pc	Frt Support Panel		\$ CM 783.20 ✓
8	2 pcs	Headlamp L/R <i>6550</i>	<i>mg CM</i> \$ 594.20	\$ 1,188.40 ✓
9	1 pc	Rear Boot Lid		\$ Pm 886.00 ✓
10	2 pcs	Rear Boot Lid Reflector Lamp L/R	\$ 126.20	\$ Pm 252.40 X
11	1 pc	Rear Boot Lid Outer Mouldin		\$ Wm 136.50 ✓
12	1 pc	Rear Boot Lid Avante Emblem		\$ Pm 32.50 ✓
13	1 pc	Rear Boot Lid S Emblem		\$ Pm 25.60 ✓
14	1 pc	Rear Boot Lid Hyundai Logo		\$ Pm 32.90 ✓
15	1 pc	Rear Boot Lid Mechanism Lock		\$ Pm 168.00 ✓
16	1 pc	Rear Boot Lid Inner Upholstry Trim		\$ Pm 126.40 X
17	2 pcs	Rear Boot Lid Hinges L/R	\$ 112.70	\$ Pm 225.40 X
18	1 pc	Rear Bumper <i>489</i>		\$ Pm 582.20 ✓
19	2 pcs	Rear Bumper Side Holder L/R	\$ 42.30	\$ Pm 84.60 X
20	1 pc	Rear Bumper Reinforcement		\$ CM 286.20 ✓
21	2 pcs	Rear Bumper Bracket L/R	<i>ml Pm</i> \$ 78.30	\$ 156.60 ✓
22	1 pc	Rear Bumper Inner Foam <i>108.20</i>		\$ CM 141.40 ✓
23	1 pc	Rear End Panel		\$ Pm 485.10 ✓
24	1 pc	Rear End Panel Top Garnish	<i>59.255m</i>	\$ Pm 89.30 ✓
25	1 pc	Rear Boot Weatherstrip	<i>o/s CM</i>	\$ 118.50 ✓
26	2 pcs	Rear lamp L/R	\$ 326.20	\$ 652.40 ✓
				\$ 8,022.40
				Less 20%
				\$ 1,604.48
				Parts Total : \$ 6,417.92

Special Nett				
1	1 pc	Frt License Plate		\$ Pm 50.00 <i>455m</i>
2	1 pc	Rear License Plate		\$ Pm 50.00 X
3	1 set	Frt Bumper Clips		\$ Pm 45.00 ✓
4	1 set	Frt Grille Clips		\$ Pm 35.00 ✓
5	1 set	Rear Bumper Clips		\$ Pm 45.00 ✓
6	1 set	End Panel Garnish Clips		\$ Pm 35.00 ✓
7	1 set	Reverse Sensor		\$ Short 250.00 <i>2001m</i>
Special Nett :				\$ 510.00

Labour

1	To remove & rearrange electrical wirings, check lightings	\$	100.00	401
2	To remove & replace upholstery, trim garnishes to facilitate repairs.	\$	100.00	501
3	To remove, & transfer boot lid components.	\$	80.00	501
4	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$	1,000.00	8001
5	Putty and respray painting on affected portions.	\$	1,200.00	8001
6	To remove & renew reverse sensor	\$	100.00	501
7	Rust proofing on affected portions.	\$	100.00	601
Labour Total :		\$	2,680.00	
Total Parts & Labour :		\$	9,607.92	



for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: