



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: HELENA TAN			Ref: CS/INC23000303/Rqy3e2 Date: 23/03/2023 Code: INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLK 1370A	Veh. Inspected	SLL 7895H	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1203596-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	10/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11208292	Colour	BLUE	
Odometer	172584 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	6 mm	
L/H Front Tyre	215/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/01/2023	Inspection Date	10/01/2023	
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	